

# REPAIR OR REPLACEMENT ORDER

No. 30397

☒ WARSHAL'S SPORTING GOODS CO.

1000 - 1st AVE.  
604-7200

Seattle, Wash. 98104 *Dec 24 1979* *TS*  
Ship to *REMINGTON ARMS CO.*  
*ARMS SERVICE DIVISION*  
*ILION NY 13357*  
Article *ONE REM 700 # A6696592 CAL 12MM EXPRESS*

*THIS GUN INVOLVED IN ACCIDENT. CUSTOMER SAYS*  
*FIRE ON OPENING HITTING A PICKUP TRUCK*  
*CUSTOMER IS* *LR BLAUF M PARKER*

*15022 SE 15th*  
*BELLEVUE WASH 98004*

☐ REPAIR

☐ REPLACE

*STORE STOCK*

☒ Prepaid ☐ Collect

VALUE: \$ *330.00*

☒ Main ☐ Stock

☐ Northwest ☐

Customer

Address

Tel. No.

CONSIGNED COPY

pany. Trigger pull was well within our specifications at 4 1/2 pounds.

Based on our findings, Remington Arms Company, Inc., cannot accept any liability or responsibility for the incident. We can only assume that at the instant the bolt was grasped, accidental contact was made with the trigger, causing the gun to fire.