

PS160
REMINGTON ARMS
ARMS SERVICE DIV.

ILION, N.Y. 13357

L. WATSON
6113 LOCKAMY LN
NORFOLK, VA 23502

RECEIVED

FEB - 1, 1985

J. A. STEKL

Dear Sir,

RECEIVED

FEB - 1 1985

ARMS SERVICE

I'm writing this to
comment on your Model 700
rifle. I recently was a by-stander
when one of your rifles was accidentally
discharged while being loaded. The
rifle had been pointed in a safe
direction so no injury resulted.

I realize that the fault was with
the shooter but if your Model 700
rifle had the old style safety
(3 position) lock, safe & fire this
would not have occurred. I
have many guns some of which are
bolt action and have never seen
one where the safe must be off
to load & unload as ^{on} your Mod. 700.