

**DON'T SAY IT-WRITE IT**

To R. H. P. Location IM Portant  
From J. A. S. Location \_\_\_\_\_ Phone No. \_\_\_\_\_  
Subject \_\_\_\_\_ Date 12/31/24

Please respond to attached letter -

- 1.) M700 has had same trigger & performed satisfactorily for 23 years
- 2.) Generally, accidental firing results from: a) improper maintenance of rifle, b) improper adjustment of trigger assembly out of factory, or, c) inadvertent contact with trigger as safety is released
- 3.) offer no-charge replacement of trigger assembly (as good-will gesture) with new-style assembly.
- 4.) Have gun sent to Arms Service directly for work.