

RECEIVED

FEB 13 1985

CONSUMER SERVICE

February 5, 1985

Remington Arms Company, Inc.
Bridgeport, Connecticut 06602

Gentlemen:

I own a 700 ADL, 30-06 serial # 6715549.

My brother, an experienced hunter and rifleman was using it to deer hunt last December. The temperature was in the low 30's and it was dry. As he was unloading the rifle, holding it by the forstock and ejecting the live rounds onto the seat of his Ford pickup, the rifle fired as he closed the bolt on the last round. As you may expect, he did not hear well for awhile. The door of his truck has a large hole in it and the muzzle blast ripped his seat for about 6 inches. The only other damage was to his nerves and the pants he had on. The pants were disposed of post haste.

Seriously though, I am afraid if my rifle fired in this manner that others may do it also.

Do you have any suggestions as to a fix for it.

Sincerely,

William R. Weaver

William R. Weaver

WRW
nw

PPS 05374