

April 10, 1991

Remington Arms Inc.
Arms Service Division
Ilion, NY 13357


RE: Remington 700BDL; Serial Number A6814285

Dear Sirs;

The above mentioned 30.06 deer rifle that was purchased about 12 years ago has malfunctioned on two separate occasions when I would take the safety off to unload the chamber round the gun fired the instant I pushed the safety off. The last time this occurred was in 1990. The time before that was 1989. Both times I was deer hunting. I took the gun to a gun smith and had it thoroughly cleaned and checked. The gun smith stated that the screws had not been tampered with on the trigger mechanism and he thought the gun was OK.

I had visited with another gun smith in another city and he stated Remington had had some problems with it malfunctioning like this and Remington had made a recall to repair this problem. Would you please advise me as to what to do because I do not want an accident to occur and kill someone and make both Remington and myself liable for litigation? Enclosed is a self addressed stamped envelope for your reply.

Sincerely,



H. W. Weldon

HWW:ew

Enc.

*P.S. I just visited with arm service Div.
They told me to send you for replacement trigger parts.
I would appreciate a letter explaining what happened
and assurances will not happen again.*