

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 92-21176

W/FLOOR PLATE, MAG 7.62x39 SPG, FOLLOWER, SCREWS

STEEL

INITIAL JJM	CUSTOMER ORDER NO.		DATE RECEIVED 10/07/92		DATE OPENED 10/13/92	DATE CODE XA 12-80	SERIAL NUMBER B6277333	NEW SERIAL NUMBER	MODEL AND GRADE 700 7MMAG
ACCESSORIES		L/WOOD	SCOPE MNTS	SCOPE BASE	L/SIGHTS				

FROM:	SHIP TO:
WEIR, NOLAN R GREEN ACRES I P O BOX 21 POINT BLANK TX 77364	WEIR, NOLAN R GREEN ACRES I P O BOX 21 POINT BLANK TX 77364
CUST NO: 068132 C.O.D.L	

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	PROM. DATE	ESTIMATED	VIA
						UPS
GUN CONDITION						REPAIR CHARGE
☐ NEW ☐ LIGHTLY WORN ☐ WORN ☐ VERY WORN ☐ UNREPAIRABLE ☐ MARRED						EXCISE TAX INSURANCE UPS PARCEL POST TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
RIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4			E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT: No fault found - cannot duplicate complaint. Rifle and trigger assembly operate properly in every regard.

Trigger pull 4.5 pounds; rear lift .007"

RTS	COMMENTS					
	Offer the following options: 1) Return rifle as-is 2) Install a new trigger assembly at normal cost, as a gesture of goodwill, if that would better restore confidence in the rifle					
	REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
	GALLERY TESTER	DATE	DATE	DATE	DATE	DATE