

RECEIVING AND ESTIMATING REPORT

CUST NO: 047018 C.O.D		COMMENTS			
INITIAL JM	CUSTOMER ORDER NO.				
DATE RECEIVED 7/29/91	DATE OPENED 08/05/91	DATE CODE EU 10-71	SERIAL NUMBER 6485398	MODEL AND GRADE 700 300WIN	ORDER R 91-14967
ACCESSORIES W/STUDS		SCOPE BASE		L/SIGHTS	

FROM:	SHIP TO:
WHIPPLE, CHARLES A 16 OLD BROOK STATION RD P O BOX 679 PRINCETON MA 01541 USA	WHIPPLE, CHARLES A 16 OLD BROOK STATION RD P O BOX 679 PRINCETON MA 01541 USA

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐ CLEAN/TEST	PROM. DATE	ESTIMATED 8-26-91	VIA V463597633
----------------	--------------------	---	------------	----------------------	-------------------

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
---------------	-----	-----------	-----	-------------	-------

GUN CONDITION:	☐ NEW	☒ SLIGHTLY WORN	☐ VERY WORN	☐ MISUSED	☒ MARRED
----------------	------------------------------	---	------------------------------------	----------------------------------	--

CUSTOMER'S REQUEST

Fired accidentally when I moved safety to off.

MAIN FAULT: *Cannot duplicate reported incident, however, trigger assembly has been improperly adjusted out of spec - trigger pull 2.5# (below spec.) overtravel excessive. Trigger assembly contaminated with partially dried lubrication. Rifle has no top to bottom of receiver. Surprisingly maintained.*

ARTS	<i>Offer to clean and re-adjust present trigger assembly (if possible) Or, we can install a new trigger assembly at a normal cost, as a gesture of good-will.</i>					
REPAIRMAN DE	PROOF	CLEAN	TEST	TARGET	PATTERN	
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE	

OFFICE COPY

RD6925 REV. 7/90

PPS 05421