

COMMENTS

ORDER
92-07318

FROM:		SHIP TO:
WILDERNESS SPORTS II		WILDERNESS SPORTS II
331 RIVER RD		331 RIVER RD
P O BOX 246		P O BOX 246
WILLINGTON	CT 06279	WILLINGTON
		CT 06279

CUST NO:040659 CJO.D

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	PROM. DATE	ESTIMATED	VIA	UPS
GUN CONDITION ☐ NEW ☐ LIGHTLY WORN ☐ WORN ☐ VERY WORN ☐ UNREPAIRABLE						REPAIR CHARGE	
						EXCISE	
						TAX	
						INSURANCE	
						UPS	
						PARCEL POST	
						TOTAL	

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	Fired when closing bolt				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT

MAIN FAULT Right invariable as received. Top gear assembly has been
improperly adjusted, out of factory - original design gone from
adjusting screws. 1) insufficient gear engagement 2) insufficient
oil travel - oil will not come upon sliding ball.

[illegible]

OFFICE COPY

RD6925 REV. 8.1

PPS 05479