

REC'D'ING AND ESTIMATING REPORT

COMMENTS

60 Minute

☒ R

ORDER

94-11305

NITEL CUSTOMER ORDER NO.

FPS

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

03/29/94

03/30/94

BW 1-72

6513252

700

30-06

ACCESSORIES

L/WOOD

L/FOLLOWER

L/MAG SPRING

SCOPE BASE

ROM:

SHIP TO:

WILLMENG, WAYNE
2743 SOUTH 41ST STREET
LINCOLN NE 68506

WILLMENG, WAYNE
2743 SOUTH 41ST STREET
LINCOLN NE 68506

CUST NO: 095083 C.O.D.

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

PROM. DATE

ESTIMATED

VIA

UPS

GUN CONDITION

☐ NEW

☐ LIGHTLY WORN

☒ WORN

☐ VERY WORN

☐ UNREPAIRABLE

☐ MARRED

Product Service

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

B1

TRIGGER GROUP

BOLT ASSY.

BARREL ASSY.

REC. ASSY.

WOOD

METAL

MAIN FAULT

Trigger on returning safety - 60 Minute
Article said that firearms of my age
had the same problem
Mfg 1-72 Factory sear missing on trigger sear engagement screw. Sear engagement altered outside of factory. Replace trigger assy. at special price as gesture of good will. Do not recommend that the trigger be adjusted outside of the factory.

ARTS

COMMENTS

Trigger pull measured 2 3/4
as Rec'd.
Sear lift measured as Rec'd.
Sear engagement measured .010

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 1/94

PPS 05525