

1980

2 1/4 lbs tissue full below min. factory spec.
007 Spec left OK.

Sealant removed and 3 replacement done
indicated it was temporary with 1/5 fabric

When covered with grey sticky substance - not good
showing

Change 1/2 normal replacement cost new
TA & Clean action

\$2.00 to get into & good work

plus supply