

RECEIVING AND ESTIMATING REPORT

COMMENTS

Full Size

ORDER
R 93-22487

CUSTOMER ORDER NO.

BOTTOM HALF OF MOUNTS ONLY

Product Service

RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
19/93	10/21/93	DX 9-73	6668023		700 7MMAG BDL/LH
W/STUDS		SCOPE BASE		L/SIGHTS	

SHIP TO:

WILSON, ALBERT F
RT 8 BOX 580
CROSSVILLE

TN 38555

WILSON, ALBERT F
RT 8 BOX 580
CROSSVILLE

TN
38555

CUST NO: 085783 C.O.D.

INT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	PROM. DATE	ESTIMATED	VIA
				11/5/93	UPS
CONDITION					REPAIR CHARGE
W					25.00
SLIGHTLY WORN					EXCISE
ORN					TAX
SLIGHTLY WORN					INSURANCE
REPAIRABLE				UPS	
REPAIRABLE				PARCEL POST	
REPAIRABLE				TOTAL	

COMPONENT CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
E	A1	B1				
GROUP		B2	FIRED IN HORN FLIPPED ON SAFE			
ASSY.		B3		E2	F2	
REL ASSY.		B4		D1	E3	F3
ASSY.		B5		D2	E4	F4
D			C1	D3	E5	F5
AL			C2			

FAULT: SEND TO PRODUCT SERVICE Rifle Mfg 1973
 Trouble to duplicate concern. Examination revealed heavy build up of sludge
 in action and trigger assembly. Sludge has been removed from the
 gas adjustment and stop adjustment screw, indicating they have been
 tampered with. Both screws have been checked out.

COMMENTS

*Replace complete trigger assembly &
 clean action at 1/2 normal replacement
 cost, as question of good will
 go ahead*

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
122		✓	✓		
GALLERY TESTER	DATE	DATE			DATE

RD6925 REV 1/92

PPS 05532