

P.I. No GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700
GENERAL CONDITION: Good R #: 22234
OUTSIDE WORK: TRIGGER SCREWS READJUSTED DATE: 12/7/67
FROM: WISLER WESTERN
ARMS INC
705 SECOND ST
SAN FRANCISCO CAL
FIRED AMMO TYPE: UNKNOWN GUN #: 300523
& CONDITION: _____
PROOF: (REP) INSP.: 14 TEST: 58 [REDACTED] 8-67
HEADING: OK [REDACTED] 20 WIN
BREECH OPENING: _____ CHECKED BY: SM T.
RECOIL SHOULDERS: NORMAL APPROVED: [Signature]
CHAMBER: _____ APPROVED: [Signature] 1/3/68
TEST: _____ APPROVED: _____
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

STOCK CRACKED, BUTT PLATE MISSING, MAGAZINE
BOX DEFORMED

GUN FIRED WHEN SAFE WAS MOVED TO
POSITION (PER CUSTOMER)

INCIDENT: GUN APPARENTLY FIRED WHEN SAFE WAS RELEASED AND
TRIGGER INADVERTENTLY PULLED AT SAME TIME OR GUN WAS
HIT CAUSING JAR OFF DUE TO IMPROPER SETTING.

COMMENTS: SEAL WAS REMOVED FROM TRIG. ADJUSTING SCREW AND EN-
GAGEMENT SET LESS THAN RECOMMENDED. 0.20 MIN. ENGAGEMENT
SCREW ALSO SHOWS EVIDENCE OF HAVING BEEN MOVED
TRIGGER PULL WAS CHANGED SO THAT NOW IT IS APPROXIMATE
1 1/2 LBS. EVEN SO, WAS NOT ABLE TO MAKE GUN FOLLOW -
DOWN AT PRESENT SETTING AS CUSTOMER MAINTAINS.