

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 91-25098

INITIAL	CUSTOMER ORDER NO.	L/FLOOR PLATE, SCREWS			
LCS					
DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
12/03/91	12/05/91	DX 9-73	6671711		700 243 WIN
ACCESSORIES L/WOOD L/FOLLOWER L/MAG SPRING L/SIGHTS					

FROM:

SHIP TO:

WORLD TRADE TRANSPORT CORP
OF VA
22 EXPORT DRIVE
STERLING VA 22170
USA

WORLD TRADE TRANSPORT CORP
OF VA
22 EXPORT DRIVE
STERLING VA 22170
USA

CUST NO: 054141 C.O.D

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐ CLEAN/TEST	PROM. DATE	ESTIMATED	VIA
					UPS
GUN CONDITION			REPAIR CHARGE		
☐ NEW			EXCISE		
☐ LIGHTLY WORN			TAX		
☐ WORN			INSURANCE		
☐ VERY WORN			UPS		
☐ UNREPAIRABLE			PARCEL POST		
			TOTAL		

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	1) Rifle fired upon moving safety off				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		2) Bolt handle knob broken off - indication of			E2	
BARREL ASSY.		high pressure load		D1	E3	F3
REC. ASSY.				D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT

- 1) Trigger assembly has been improperly adjusted out of factory
a) excessive over-travel b) excessive rear engagement - cannot double
complaint however
2) Bolt handle broken off with apparent high-pressure handload.

PARTS	COMMENTS				
	1) replace bolt - standard charge				
	2) offer to price trigger assembly replacement at genuine good will.				
	Note - Per attached letter, call Jack Moore with quotation price (703) 450-6800				
REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
BW					
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 8/

PPS 05592