

REPAIR GUN UPDATE FUNCTION: I (N)EXT (P)REV (U)PDATE (I)NQ (E)XACT 03/26/93
ENTER REPAIR NUMBER -----> 9303819 14 14 24
SERIAL NO: 119540 NEW SERIAL NO: MODEL: 700
FROM: (CUST NUM: 075041) WORRALLGER GA/CAL: 30-06
HUGHES, JOHN TYPE: ADL
708 HIGH STREET ACCESSORIES:

POTTSTOWN PA 19464
SHIPPED TO:
JOHN HUGES
208 HIGH ST
POTTSTOWN PA 19464
COMMENTS: ATTN R POTTER

DATE CODES: DL 9-64 2ND TIME IN
OTHER ACCESSORIES:

DATES: TO FROM
RECEIVED 01 27 93 BATTERY 02 11 93 02 18 93 ENTERED BY: JJM
OPENED 02 05 93 PROD SERV 00 00 00 00 00 00 REPAIRMAN: JJB
ESTIMATED 00 00 00 TAG GUNS 00 00 TYPYST:
PROMISED 00 00 00 REJECTED 00 00 CORRESPONDENT:
REPAIRED 00 00 00 CASH RECEIVED:\$ 0.00 BILL TYPE: D
SHIPPED 02 19 93
BILL TYPE COD PF1=VIEW DETAIL PF2=REPRINT R&E PF3=PRINT R&E PFS=CUST MAIN

REPAIR NUMBER: 9303819 CHARGE (AWAIT RESP) COD PRINTED 03/26/93
CUSTOMER NAME: HUGHES, JOHN 14 15 40

REQUEST: GUN ACCIDENTLY DISCHARGED - SEE LETTER
MAIN FAULT: UNABLE TO DUPLICATE CUSTOMERS CONCERN. HOWEVER, EXAMINATION
REVEALED THAT THE TRIGGER ASSEMBLY IS COVERED WITH STICKY
SUBSTANCE. SEAR SAFETY CAM SLUGGISH. ACTION NEEDS GOOD
CLEANING. TRIG PULL 4 1/2 LBS. -
DATE OF MFG: 1964

PARTS: \$ 28.50 1 26345 TRIGGER ASSEM RH
\$ 0.00 19900005 TEST
\$ 0.00 19900004 CLEAN
LABOR: \$ 0.00 POLISHED CHAMBER
\$ 0.00 REPLACE TRIGGER ASSEMBLY AT 1/2 NORMAL REPLACEMENT COST
\$ 0.00 AND CLEAN ACTION.
\$ 0.00 CUSTOMER APPROVED PER PHONE 02/05/93
\$ 0.00 CALLED 2/10/93 CHANGED SHIP TO ADDRESS
\$ 0.00 JJB/HAR

REPAIRMAN'S INITS: JJB NUM OF WKS: 04 CORRESPONDENT'S INITS:
TOTAL VALUE:\$ 38.21 PF1 = INQ PF2 = ESTIMATE
NO MORE DATA AVAILABLE FOR THIS REPAIR

3/26/93 to Fun Cole
Found in ammo box address wrong
re-shipping 3/29/93