

RECEIVING AND ESTIMATING REPORT

COMMENTS

60 minutes PD

R

ORDER 94-14317

INITIAL CUSTOMER ORDER NO.

FPS

ATTN: JACK KAST

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

04/26/94

04/27/94

LB 2-81

B6303919

700 30-06

BOL

ACCESSORIES

SLING STRAP

W/STUDS

W/SWIVELS

FROM:

WUHRER, ANDREW A.
21 DROVER ROAD
BROOKFIELD

CT 06804

SHIP TO:

WUHRER, ANDREW A.
21 DROVER ROAD
BROOKFIELD

CT 06804

203-354-2226

CUST NO: 096577 C.O.D.

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

059015

WRITE ☐

PROM. DATE

ESTIMATED

VIA

UPS

UN CONDITION

☐ NEW

☒ LIGHTLY WORN

☐ WORN

☐ VERY WORN

☐ UNREPAIRABLE

☐ MARRED

Go ahead per phone 5/2 last

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

TRIGGER GROUP

B1

BOLT ASSY.

B3

BARREL ASSY.

B4

REC. ASSY.

B5

WOOD

C1

D3

E5

F5

METAL

C2

MAIN FAULT

11/2/82 Unable to duplicate customer concern as received. The trigger pull screw has been adjusted outside of factory exchange trigger assy at N/C strictly as a gesture of good will and to restore customer confidence in rifle.

ARTS

COMMENTS

Trigger pull measured 2 1/2 to 4 lbs. as received seat lift measure 0.105 last

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 1/94

PPS 05601