

Remington.



REMINGTON ARMS COMPANY, INC.

SPORTING ARMS-AMMUNITION-TARGETS-TRAPS

ILION, NEW YORK 13357

TELEPHONE (315) 894-9961

April 9, 1985

Mr. C.M. Zimmerman, Jr.
1221 43½ Ave., N.E.
Minneapolis, MN 55421

Dear Mr. Zimmerman:

This is in reply to your March 19 letter regarding the trigger assembly modification for your Model XP-100 in 221 caliber, serial number 5439.

If your Model XP-100 has a zero (o) stamped on the tang of the receiver, the handgun has already been modified and you need not take any action. Otherwise, your firearm is under recall.

Please send your Model XP-100 via UPS, transportation COD to:

Remington Arms Co., Inc.
Arms Service Div.
Ilion, NY 13357

In order to perform the modification, we will need your rebarreled barreled action and the original Model XP-100 stock. Also, please mark the package "XP-100 modification" and allow two (2) months for turnover time.

Enclosed as requested is a Model XP-100 owner's manual including parts list.

Thanks for your cooperation in this important matter, Mr. Zimmerman, and for your continued support.

Sincerely,

R.H. Potter, Supervisor
Product Service

RHP:tpg
encl.

PPS 05653