

R# 06332

P.I. No

MFD. 8-78

Number

6-9-83

THIS GUN WAS CRACKED, ITS SAFETY WAS SWITCH TO THE "S" POSITION, AND IT WAS PLACED INSIDE A COLD BOX (INSIDE THERMOMETER INDICATED -30F) AT 4:35 P.M. ON 06 APRIL 83.

UPON REMOVAL OF THIS GUN FROM THE COLD BOX (INSIDE THERMOMETER INDICATED -29F) AT 9:40 A.M. ON 07 APRIL 83.

THE FOLLOWING TEST WAS IMMEDIATELY PERFORMED:

- ① Pull trigger to see if it finds or sticks back —
IT DID NEITHER!

- ② Switch safety to "F" position - IT DID NOT FIRE-DOWN.

- ③ Open bill and check for errors - NONE

- ④ Close bolt and work plate - POSITIVE, SNAPPY ACTION.

- ⑤ Switched safety to "S" position, pull back hard on trigger, release trigger, switch safety to "F" position. Repeat this three times. — THE FIRING PIN DID NOT FIRE-DOWN.

- ⑥ With safety switched to "F" position, pull trigger.
— THE FIRING PIN FIRED-DOWN. THE FIRST TIME IT FIRED-DOWN

SLUGGISHLY AND SUBSEQUENT FIRE-DOWNS WERE SNAPPY.

- ⑦ Loosen the bolt and repeat the entire test. - No

PROBLEMS ENCOUNTERED AND NO F.S.R. OBSERVED.

- ⑨ Perform "trick test". — GUN PASSED THE "TRICK TEST".