

Customer Complaint

P.I. No GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 BDL
GENERAL CONDITION: NEW R #: 23406
OUTSIDE WORK: No DATE: 11-2-70
FROM: OCONTO, WIS.
FIRED AMMO TYPE: -
& CONDITION: _____ GUN #: 6248578
PROOF: - INSP.: _____ TEST: _____ CODE: PS = 6/69
HEADING: - GA./CAL.: 7MM
BREECH OPENING: - CHECKED BY: C. PROSSER
RECOIL SHOULDERS: - APPROVED: _____
CHAMBER: - APPROVED: _____
TEST: No APPROVED: _____
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

TRIGGER CONNECTOR BROKEN.

COMPLAINT: FIRES WHEN SAFE IS REMOVED & WONT COCK
AT TIMES.

INCIDENT: _____

COMMENTS: MALFUNCTION WAS CAUSED BY THE BROKEN
TRIGGER CONNECTOR.