

P.I. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 BDL
GENERAL CONDITION: NEW R #: 22570
OUTSIDE WORK: NO DATE: 11-2-70
FROM: LIMA, OHIO
FIRED AMMO TYPE: —
& CONDITION: _____ GUN #: 6233914
PROOF: — INSP.: _____ TEST: _____ CODE: CS = 4/69
HEADING: — GA./CAL.: 222
BREECH OPENING: — CHECKED BY: C. PROSSER
RECOIL SHOULDERS: — APPROVED: _____
CHAMBER: — APPROVED: _____
TEST: NO APPROVED: _____
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

O.K.

COMPLAINT: FIRES WHEN SAFE IS RELEASED.

INCIDENT: TRIGGER CONNECTOR MOVES UP WHEN TRIGGER IS
PULLED WITH THE SAFETY ON.

COMMENTS: TRIGGER CONNECTOR IS .007 OVERSIZE ON TRIGGER
CLEARANCE. TRIGGER IS .006 UNDERSIZE ON CONNECTOR
CLEARANCE. THIS EXCESSIVE CLEARANCE ALLOWS THE
CONNECTOR TO WORK UP, INTERFERE WITH THE SEAR AND
FAIL TO RETRACT UNDER THE SEAR RESULTING IN
FOLLOW DOWN WHEN THE SAFETY IS PUSHED OFF.