

Remington Arms Co., Inc.
Product Service
Legal Case #:623

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
120222	11/15/2006	11/17/2006	11/17/2006				X

Customer Information

Type	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	Robert	Schott	2506 Galicia	LaVerne	CA	91750		H 951-218-1310 F 909-596-9992 E bschott@verizon.net

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD				
S	Cause:4006 Fires on bolt closing	Altered Adjustments or Components Concern:1008 Fired on Bolt Closing	Unknown	
C				

11/22/06-correspondence with firearm-Gun fires when closing action or moving safety to fire position.lw

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
REMINGTON	CF/BA	600/308 WIN		6596	LL	2/1/1964
Date Purchased	Where Purchased	Accessories	Original Owner			
		SCOPE BASE	U			

CUST.CONCERN:FBC

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

REMINGTON/600/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Replace TA at n/c under recall						
	Repair/Replacement Cost	Repair/Replacement Date				
	\$25.00	11/22/2006				

11/22/06-Trigger assembly misassembled outside of factory and has not been updated. Replace TA under recall at n/c. Check over and clean.lw

PS 7144

Examination[REMINGTON/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		11/17/2006
	Product Type		RF
	Action Type		A
	Assigned To		F.SUPRY
Cause	4006	Altered Adjustments or Components	TRIGGER ASSM HAS BEEN MISASSM OUTSIDE OF THE FACTORY
Barrel	Description		18.5" 308 WIN VT
	Date Code		LL
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Worn; Functioning	
	Stock Condition	Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	

PS 7145

	Bulged	False	
Safety	Description		STANDARD M/600 BOLT LOCK SAFETY
	Function	Slightly Worn; Not Functioning	
Sear	Lift	---Select---	N/A
	Notch	Slightly Worn; Not Functioning	
Tests	Test Fired	False	
	Feeding Test	False	
Trigger	Condition	Abused; Not Functioning	HAS BEEN MISASSM OUTSIDE FACTORY
	Pull	---Select---	N/A
	Altered	True	
Non-Remington Components	Description		SCOPE BASE

PS 7146

CASH
623

General Repair Form

Back to Repair Services

NOTE: Please complete and print this form, and then include it with your firearm

LL 2/64

Model Number: 600		Serial Number: 6596	
Name: Robert Schott		Date of Purchase: Late 1970's	
Address (no PO Boxes): 2506 Galicia			
City: La Verne		State: CA	Zip: 91750
Phone (Daytime): 951-218-1310		Fax: 909-596-9992	
E-mail Address: bschott@verizon.net			
Please describe your problem: Gun fires when closing action or moving safety to fire position.			
436 characters left			
NOTE: Prior to shipping your firearm, contact the Repair Center for services provided and estimated repair time.			
Ⓢ WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.			
:: Record the serial number of your firearm before sending it. :: Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.) :: Remove all accessories from your firearm to prevent loss or damage. :: Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for damage or loss during shipment, so you may elect to purchase insurance from your carrier.			

OBSOLETE RIFLE ✓

©2005 Remington Arms Company, Inc. All Rights Reserved. | Legal Notices

Remington

Serial Number:

6596

Model: 600



RE00120222

T779. ASSM mis ASSM outside of
 factory + has not been updated.
 replace TPA under min 11 at M/K
 check over release
 15 230145.

(PS 7147)

Arms Services Repair & Estimate System

File Add Repair Estimate Repair Expedite Repair Inquiry Repair Tools CSR Tools Reports Table Maintenance System Maintenance Help

Repair Inquiry

Repair Number: RE00120222

Serial: 6596 Model 600 Center Fire Caliber: 308 WIN

Repairman:

Verify Repair

Status:

New 11/14/2006 8:53:19 AM

Address Information

Customer:

☒ Received From

Return To:

☐ Received From

Name: ROBERT SCHOTT

ROBERT SCHOTT

Address 1: 2506 GALICIA

2506 GALICIA

Address 2: PO Box:

PO Box:

City: LA VERNE

LA VERNE

State: CA Zip Code: 91750

Country: US

State: CA Zip Code: 91750

Country: US

FFL:

Contact / Condition

Problems

Estimate

History / Status

Shipping / Billing

Problems Reported

Code	Desc
M123	FORWARD TO PRODUCT SE
M240	BOLT LOCK SAFETY MODIFI
M990	GUN FIRES WHEN CLOSING

Repair Notes

Repairman's Comments

Problems Found

Code	Desc

CSR Comments

Repair Search

Refresh

Close

PS 7148

ImWatson

11/22/2006

9:09 AM

CAPS

NUM

INS

SCRL

Start

2 Micro...

Arms Se...

2 Inter...

Search fo...

700.Tho...

Microsoft...

P-touch E...

FullShot 97

100%

<<

>>

9:09 AM

Remington Arms Co., Inc.
Product Service
Legal Case #:748

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
		11/28/2006		11/25/2006			

Customer Information

Type	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	Larry	Rhodes	85 Amethyst Rd	Palmyra	VA	22963		W 434-973-1351 x4227 C 434-989-6320

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Shot hole in truck and transmission	Cause:4079 Other - Unexamined		
S	Concern:1025	Unexplained Discharge - No Mention of Safety Position	Unknown	
C				

11/28/06-Cust. had rifle loaded in vehicle. Picked up the gun by the stock and the gun went off in the truck and blew a hole in his transmission. No injuries occurred. Vehicle was a 2000 S10 ZR2 off road. He estimates that this will be approximately \$2000 for a new transmission. Cust owns several M/ 600 rifles and did not know about the recall. lw Serial numbers: 600/243win/6849681(incident gun) 600/222rem/6415380 600/308win/60808 600/308win/62575 660/22-250/129668

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	600/243win.	20000	6849681		1/1/1900
Date Purchased	Where Purchased	Accessories	Original Owner			
	LESLIE EDELMAN SOUTHAMPTON PA		U			

11/28/06-Cust has 3 other M/ 600 rifles and a M/660(which has been rechambered). I advised customer that these all could be under recall. Notated to him to check for the "V" stamp on the trigger to see if its been taken care of.

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/600/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
					PS 7149	
	Repair/Replacement	Repair/Replacement				

Cost**Date**

11/29/06-sending ARS, Ltr, & box. Cust has some disabilities and will not be able to send gun until possibly after Christmas. I offered ARS & boxes for the additional firearms so we can check them for recall and safety.lw

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
------	----------	------	---------

(PS 7150)

748

Case Information				
Date of Call	Incident Date	Pre Lit	Lit	Obsolete
11/28/06	SA 11/25/06			X
Customer Information				
Name	Reporter (Age)	Incident (Age)		
Lamy Rhodes				
Address	85 Amethyst Rd			
City, St Zip	Palmyra, VA 22963			
Home				
Cell	434-989-6320			
Work	434-973-1351 x 4227			
Incident Information				
Personal Injury <input type="checkbox"/>	Property Damage <input checked="" type="checkbox"/>	Safety <input type="checkbox"/>	Concern <input type="checkbox"/>	
Nature of Injury: NONE				
Medical Treatment:				
Claim:				
Incident: P/U gun by stock				
gun went off in truck + transmission				
2000 510 202 off road				
<div style="float: right;"> - Send boxes ARS for incident gun. - Cust to check others for recall stamp on trigger </div>				
<div style="float: right;"> Mohawk 600 222 6415380 600 308 60808 600 308 62575 transmission recharged 600 22-250 129668 </div>				
\$2000 for damage to truck				
Firearm Information				
Manufacturer	Type of Action	Model/Cal. or Ga.	Serial Number	Date of manuf.
Rem	B/A	600/243	6849681 Mohawk	
Date Purchased	Where Purchased		Original Owner	
Ammunition Information				
Factory or Reloads				
Manufacturer				
Caliber				
Bullet type				
Bullet Weight				
Lot # of ammunition				
Additional Ammo Info:				
Other Products Information				


box - 814138
ARS ✓

LARRY RHODES
85 AMETHYST RD
PALMYRA VA 22963

10 LBS
RS

1 OF 1

SHIP TO:
ATTN: PRODUCT SERVICES
REMINGTON ARMS CO INC
14 HOEFLE AVE
ILION NY 13357




NY 135 0-01



UPS GROUND

TRACKING #: 1Z 4XX 596 90 6795 1627



BILLING: 3RD PARTY
DESC:
RETURN SERVICE

REF 1: LARRY RHODES/LW
REF 2: REF# 6849681

UOM 0.0.16 UPS Thermal 2 68.1A 10/2006



International Shipping Notice - Consignee must be subject to the same liability to liability and other terms and conditions established by the Commission for the Unification of Customs Laws (CUL) to the United States of America by Air the "United States Customs and Border Protection" or the Commission of the Customs of the United States of America. For shipping prices, call 1-800-451-7878.



For more information, visit us online at www.ups.com or call 1-800-877-8652.

TO REOPEN YOUR UPS ORDER

WASH DC 20540

(PS 7153)

Remington®

November 30, 2006

Larry Rhodes
85 Amethyst Rd
Palmyra, VA 22963

Subject: Model 600 Serial #6849681
RE: Case #748

Dear Mr. Rhodes,


We were sorry to learn of the unfortunate incident that you experienced while out hunting. We are certainly glad that no one was injured, and that you are anxious to get back to enjoying the shooting sports. I understand that the round fired blew a hole in your transmission and that you will provide me with an estimate or receipt for these repairs. We can then discuss further options after evaluating the firearm.

As we discussed, I have enclosed a prepaid UPS shipping label for you to ship the firearm back to our factory for examination and repair. I have also included a copy of this letter to put inside the shipping box. (The box will come under separate cover). The letter inside is important as sometimes the outside label gets damaged in transit and we want to be sure the rifle is logged in correctly. On the factory repair form, please provide additional information about the incident, including the date of the last occurrence, type of weather, type of ammunition being used, etc.

I have also included recall information from our website so that you can check your other Model 600 & 660 rifles to see if they have been taken care of. If you do need to send the others in for the recall, please let me know and I will make arrangements for the rifles to come in to our factory. I understand that you may not be able to get these in until after the holidays and I strongly urge you to refrain from using these rifles until they have been inspected.

You have been a pleasure to speak with. We apologize for the inconvenience that this incident has caused and we hope that our actions will keep you as a loyal Remington customer.

Sincerely,



Laura Watson
Consumer Affairs Administrator
Phone: 800-243-9700 ext 8789
Fax: 336-548-7890
E-mail: laura.watson@remington.com

Remington Arms Company, Inc. • 870 Remington Drive • P.O. Box 700 • Madison, NC 27025
Phone 800-243-9700 • www.remington.com

PS 7154

Remington Arms Co., Inc.

Product Service

Legal Case #:286

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
115023	7/26/2006	7/27/2006	7/27/2006				

Customer Information

Type	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	Barretts	Batavia Marine & Sporting	411 West Main Street	Batavia	NY	14020		W 585-343-4131

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD				
Fires when	Cause:4006	Altered Adjustments or Components		
S safety is pushed off	Concern:1007	Fired on Safe Release	Unknown	
C				

Trigger assembly set screw positions altered and trigger is contaminated with a sticky substance. Firearm has never been in for the recall or updates.

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial Bbl.	DOM
REMINGTON	CF/BA	600/222 REM		40485 LN	2/1/1966
Date Purchased	Where Purchased	Accessories	Original Owner		
		SCOPE BASE - LESS REAR SIGHT	U		

CUST.CONCERN:FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

REMINGTON/600/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash	Reim. Ca Date
------------	-------------------	--------------	---------------	------	---------------

PS 7155

Settlement APV AP

New TA
n/c

Repair/Replacement Cost	Repair/Replacement Date
100.00	7/27/2006

Clean action and install new TA n/c - check over completely and complete recall/updates as required. Repair and Shipping Document 9/8/06.

Examination[REMINGTON/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		7/27/2006
	Product Type		RF
	Action Type		A
	Assigned To		F.SUPRY
Cause	4006	Altered Adjustments or Components	SET SCREWS ALTERED AND TRIG ASSM CONTAMINATED WITH A PARTIALY DRIED AND STICKY LUBRICATION RESIDUE
Barrel	Description		18" 222 REM W/RIB
	Date Code		LN
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn;	

PS 7156

		Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Worn; Functioning	
	Stock Condition	Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		STANDARD M/600 SAFETY
	Function	Like new; Functioning	
Sear	Lift	---Select---	.006
	Notch	Slightly Worn; Functioning	OLD STYLE SEAR ASSM
Tests	Test Fired	False	
	Feeding Test	False	
Trigger	Condition	Slightly Worn; Not Functioning	CONTAMINATED WITH A PARTIALY DRIED LUBRICATION RESIDUE
	Pull	---Select---	2.5#
	Altered	True	SET SCREWS ALTERED
Non-Remington Components	Description		SCOPE BASE

PS 7157

Remington Arms Company, Inc.

870 Remington Dr. P.O. Box 700
Madison, NC 27025-0700

Parts/Repairs
Fax

800-243-9700
336-548-7801

www.remington.com info@remington.com

REPAIR DOCUMENT

REPAIR DOCUMENT

Repair Order Number
RE00115023
Account # - R-

Description/Serial Number
40485

Model 600 Center Fire Caliber: 222 REM

Date Received - 7/26/2006

Estimate Date -

Current Date - 8/4/2006

Customer
BARRETTS BATAVIA MAR & SPT SUPPLIES
411 WEST MAIN STREET

BATAVIA, NY 14020 US

Return To
BARRETTS BATAVIA MAR & SPT SUPPLIES
411 WEST MAIN STREET

BATAVIA, NY 14020 US

Phone (H) (585)-343-4131
Phone (W)

Fax
Email

Problems

Reported
M123 FORWARD TO PRODUCT SERVICE
FOR INSPECTION

Found
M123 FORWARD TO PRODUCT SERVICE FOR
M176 RETURNED FOR RECALL/UPDATE

Technician's Comments

ProblemNotes Trigger assembly set screws altered and contaminated with a sticky substance. Replace trigger assembly,
check over and clean under Recall Program.

Parts and Labor

Material #	Material Description	Quantity	Warranty (Y/N)
Part			
F91469	600 TRIGGER ASSB	1	Y
Part Total:		1	
Service			
4000104	ARMS SERV SHIPPING & HANDLING	0	Y
4000118	GR-CLEAN	1	Y
4000119	GR-TEST	1	Y
Service Total:		2	

PS 7158

40485

Model: 600



RE00115023

**BARRETTS
BATAVIA MARINE
& SPORTING SUPPLIES, INC.**
411 West Main St.
BATAVIA, N.Y. 14020

CASE # 286

PURCHASE ORDER

5769

DATE 7/24/06	REQ. NO.

585 (16) 343-4131
(16) 343-4869

TO

Remington Arms

*2.5# 2/66
18"*

WHEN ORDERED		SHIP VIA	F.O.B. POINT	TERMS	
QTY. ORDERED	QTY. RECEIVED	DESCRIPTION		PRICE	AMOUNT
1	1	600/222 w/10 Rem site / w/ Bsp #40485			
Triggers fires when Safety is pushed off Please inspect					
Handgun Program H/C #230145					

- Please send _____ copies of your invoice.
- Please show this Purchase Order Number on all packages and invoices.
- Notify us immediately if you are unable to ship as specified.

RM

Authorized by

Arms Services Repair & Estimate System

File Add Repair Estimate Repair Expedite Repair Inquiry Repair Tools CSR Tools Reports Table Maintenance System Maintenance Help

Repair Inquiry

Repair Number: **RE00115023** Serial: 40485 Model: 600 Center Fire Caliber: 222 Repairman: REM Status: Closed 7/26/2006 1:10:08 PM

Priority Repair: **High Priority**

Address Information

Customer: ☒ Received From: ☐ Return To: ☒ Received From: ☐

Name: **BARRETT'S BATAVIA MAR_SPT SUPPLIES** **BARRETT'S BATAVIA MAR_SPT SUPPLIES**

Address 1: **411 WEST MAIN STREET** **411 WEST MAIN STREET**

Address 2: PO Box:

City: **BATAVIA** **BATAVIA**

State: **NY** Zip Code: **14020** Country: **US** State: **NY** Zip Code: **14020** Country: **US**

FFL: ☐

Contact / Condition **Problems** **Estimate** **History / Status** **Shipping / Billing**

Date	Code	User ID	Desc1
7/26/2006 1:08:2	New	valentds	Repair Added
7/26/2006 1:10:0	Closed	valentds	Closed at Expedite

☐ Shipping Hold ☐ Interface Hold ☐ Estimate Sent ☐ Parts Received ☐ Passed Inspection ☐ Return As Received ☐ Has been Approved ☐ Internal Repair

Current Status
Closed
7/26/2006 1:10:08 PM
valentds

Product Services
Repair Location: ILN
Current Location: ILN
Transfer Number:

Repair Search **Refresh** **Close**

supryll 7/27/2006 8:26 AM CAPS NUM INS ISCL

start Inbox - Microsoft Outlook Arms Services Repair Current Cases - Microsoft Word Microsoft Word 8:26 AM

File Number:	22153	Arms Service number:	108366
Last Name:	BATES	First Name:	TRACY
Street:	5701 WILSHIRE NE	City:	ALBUQUERQUE
State:	NM	Zip:	87113
Work Ph:		Home Ph:	505-822-9140
Product Type:	F	F A T O	
Type Concern:	S	PI PD P S	
Concern Code:	1007		
Concern:	FIRED ON SAFE RELEASE		
Cause Code:	4006	Cause:	ALTERED ADJUSTMENTS OR COMPONENTS
Assigned To:	SUPRY	Classification:	UND UNJ UNC UND J
Settlement Detail:	REPLACE TRIGGER ASSEMBLY N/C	Settlement Amount:	\$0.00
Date Opened Rem:	2/20/2006	Date Opened by P/S:	2/20/2006
Caliber:	6.5MM MAG		
Date of Incident:		Date Closed:	2/20/2006
Bullet Weight:			
Date to Analysis:		Date from Analysis:	
Manufacturer:	REM		
Model:	600	Serial:	75040
Date Code:	OO	Date Mfgd:	7/1/1977
RAMAC:	600	Litigation:	<input type="checkbox"/>
PreLitigation:	<input type="checkbox"/>	Obsolete:	<input type="checkbox"/>
Custody:		Comments:	Trigger assembly set screws altered - will not connect - Replace TPA under recall at n/c.
Time of Modification:	8:03:37 AM		
Date of Modification:	2/22/2006		

(PS 7161

7/77



General Repair Form

Back to Repair Services

NOTE: Please print and complete this form, and then include it with your firearm

Model Number: 600		Serial Number: 75040	
Name: TRACY BATES		Date of Purchase: '95	
Address (no PO Boxes): 5701 WILSHIRE NE			
City: ALBUQUERQUE		State: NM	Zip: 87113
Phone (Daytime): 505-822-9140		Fax: 505-828- 9140 1269	
E-mail Address: tracybates@QWEST.NET			
Please describe your problem:			
RIFLE FIRES WHEN RELEASING SAFETY. I DON'T			
THINK THIS RIFLE HAS HAD THE TRIGGER RECALL			
APPROX 2000 IN THE			
Additional Information: (Ammo type, brand, handload specifications, etc.)			
104366			
NOTE: Prior to shipping your firearm, contact the Repair Center for services provided and estimated repair time.			
<p>⚠ WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.</p> <p>:: Record the serial number of your firearm before sending it.</p> <p>:: Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.)</p> <p>:: Remove all accessories from your firearm to prevent loss or damage.</p> <p>:: Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for damage or loss during shipment, so you may elect to purchase insurance from your carrier.</p>			

Legal Notices

Remington

Trig. Assm. 54 screws Auted.
will not connect. Replace TPA
w/ new 11 AT N/C

/general_repair_form.asp

12/14/05

75040

del: 600



RE00108366

PS 7162

Date: 2/20/06

By: B. TIMMONS

FIREARM INSPECTION WORKSHEET

BACKGROUND

Customer name: Timothy Bates

R.E. Number: 101366

Reason for inspection: FSR

DETAILS

Manufacturer: Rum. Model: 600

Serial Number: 75040 Date of Manufacture: 7/77

Overall external condition: FAIR

Barrel condition: OKAY

Receiver condition: OKAY

Stock condition: OKAY

Bolt/firing pin condition: OKAY

Trigger assembly condition:

Engagement: ALTERED

Adjustments/alterations: ALTERED

Other: —

Headspace: —

Function evaluation:

File Number:	22189		Arms Service number:	109211	
Last Name:	GREEN		First Name:	JOHN	
Street:	161 DINKEY CHURCH ROAD		City:	LEHIGHTON	
State:	PA	Zip:	18235	Home Ph:	610-377-3339
Work Ph:		Product Type:	F	F A T O	
Type Concern:	S	PI PD P S	Concern Code:	1007	
Concern:	FIRED ON SAFE RELEASE				
Cause Code:	4015	Cause:	IMPROPER MAINTENANCE		
Assigned To:	SUPRY	Classification:	UND	UNJ UNC UND J	
Settlement Detail:	UPDATE UNDER CURRENT PROCEDURES			Settlement Amount:	\$0.00
Date Opened Rem:	2/28/2006	Date Opened by P/S:	3/1/2006	Caliber:	308
Date of Incident:		Date Closed:	3/1/2006	Bullet Weight:	
Date to Analysis:		Date from Analysis:		Manufacturer:	REM
Model:	600	Serial:	55839	Date Code:	RM
RAMAC:	600	Litigation:	<input type="checkbox"/>	PreLitigation:	<input type="checkbox"/>
Custody:		Obsolete:	<input type="checkbox"/>		
Time of Modification:	12:33:55 PM				
Date of Modification:	3/16/2006				
Comments:	TA very dirty and caked with partially dried and sticky residue. This firearm was never updated, update at n/c under current procedures. Quote for bolt replacement.				

(PS 7165)

11/05

3#



General Repair Form

Back to Repair Services

NOTE: Please print and complete this form, and then include it with your firearm

Model Number: 600		Serial Number: 55839	
Name: JOHN GREEN		Date of Purchase:	
Address (no PO Boxes): 161 DINKEY CHURCH RD			
LEHINGTON PA 18235			
City:		State:	Zip:
Phone (Daytime): 610-377-3339		Fax: —	
E-mail Address: —			
Please describe your problem: GUN DISCHARGES WHEN THE SAFETY IS TAKEN OFF			
BOLT WAS BROKEN & WELDED - WOULD LIKE A PRICE FOR ANOTHER BOLT			
Additional Information: (Ammo type, brand, handload specifications, etc.)			
NOTE: Prior to shipping your firearm, contact the Repair Center for services provided and estimated repair time.			
<p>③ WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.</p> <p>:: Record the serial number of your firearm before sending it. :: Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.) :: Remove all accessories from your firearm to prevent loss or damage. :: Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for damage or loss during shipment, so you may elect to purchase insurance from your carrier.</p>			

Legal Notices

Remington

TRIG. ASSM. URGY DIRTY & STICKY
 HAS NOT BEEN updated. Replace
 TPA, check over, clean w/ATN/C

#230145

general_repair_form.asp

1/18/2006

(PS 7166)

Serial Number: 55839

del: 600



RE00109211

Date: 3/1/06

By: B. TRAVIS

FIREARM INSPECTION WORKSHEET

BACKGROUND

Customer name: John Green

R.E. Number: 109211

Reason for inspection: FSIL

FIREARM

Manufacturer: Rum. Model: 600

Serial Number: 55839 Date of Manufacture: 11/65

Overall external condition: FAIR

Barrel condition: OKAY

Receiver condition: OKAY

Stock condition: OKAY

Bolt/firing pin condition: OKAY

Trigger assembly condition:

Engagement: —

Adjustments/alterations: ALTERED

Other: DIRTY/STICKY

Headspace: —

Function evaluation:

Feeding: _____

Extraction/ejection: _____

Trigger pull: 3rd _____

Manual safety: OKAY _____

Test firing results (if applicable): _____

DISPOSITION

TRIG. ASSM. VERY DIRTY + STICKY, HAS NOT BEEN UPDATED.

UPHOLSTRA, CHECK OVER, CLEAN AT N/C

ADDITIONAL COMMENTS

#230145

File Number:	22212		Arms Service number:	109340	
Last Name:	HURST		First Name:	RICHARD	
Street:	233 EAST 100 NORTH		City:	BLANDING	
State:	UT	Zip:	84511	Home Ph:	435-678-2960
Work Ph:		Product Type:	F	F A T O	
Type Concern:	S	PI PD P S	Concern Code:	1025	
Concern:	UNEXPLAINED DISCHARGE				
Cause Code:	4040	Cause:	OTHER - UNSPECIFIED OR UNDETERMINED		
Assigned To:	SUPRY	Classification:	UND	UNJ UNC UND J	
Settlement Detail:	UPDATE N/C		Settlement Amount:		
Date Opened Rem:	3/10/2006	Date Opened by P/S:	3/13/2006	Caliber:	243
Date of Incident:		Date Closed:	3/13/2006	Bullet Weight:	
Date to Analysis:		Date from Analysis:		Manufacturer:	REM
Model:	600 MOHAW	Serial:	6695203	Date Code:	CY
				Date Mfgd:	4/23/1974
RAMAC:	600 MOHAW	Litigation:	<input type="checkbox"/>	PreLitigation:	<input type="checkbox"/>
				Obsolete:	<input type="checkbox"/>
Custody:		Comments:	Could not duplicate concern; TA very dirty; TA not updated - update per current procedures at n/c.		
Time of Modification:	9:28:15 AM				
Date of Modification:	3/20/2006				

(PS 7169)

4/14

JH



General Repair Form

Back to Repair Services

NOTE: Please print and complete this form, and then include it with your firearm

Model Number: 600 Mohawk		Serial Number: 6695203	
Name: Richard Hurst		Date of Purchase: 7-6-05	
Address (no PO Boxes): 233 E. 100 N. #			
City: Blanding		State: UT	Zip: 84511
Phone (Daytime): 435-678-2960		Fax:	
E-mail Address: grampshurst@hotmail.com			
Please describe your problem: subject to 1999 recall program			
I bought this rifle for my 14 year old daughter to			
hunt deer. It has accidentally discharged two			
different times for her.			
Additional Information: (Ammo type, brand, handload specifications, etc.) factory loads			
NOTE: Prior to shipping your firearm, contact the Repair Center for services provided and estimated repair time.			
<p>⚠ WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.</p>			

6695203

Model: 600 MOHAWK



RE00109340

could not duplicate concern.
 TRIG. ASSM. VERY DIRTY.
 TRIG. ASSM. HAS NOT BEEN
 updated. Replace TPA, check
 very clean AT N/C

(PS 7170)

Date: 3/9/06

By: B. Timm

FIREARM INSPECTION WORKSHEET

BACKGROUND

Customer name: Richard Huast

R.E. Number: 109340

Reason for inspection: Accidental discharge

FIREARM

Manufacturer: Rm. Model: 600

Serial Number: 6695203 Date of Manufacture: 4/74

Overall external condition: FAIR

Barrel condition: okay

Receiver condition: okay

Stock condition: okay

Bolt/firing pin condition: okay

Trigger assembly condition:

Engagement: —

Adjustments/alterations: —

Other: very dirty - o/s

Headspace: —

Function evaluation:

Test firing results (if applicable): —

could not duplicate concern. TRIG. ASSM VERY DIRTY
TRIG. ASSM. has not been updated. Replace TPA, check
Owen, clean at 14K

ADDITIONAL COMMENTS

File Number:	21931		Arms Service number:	105242	
Last Name:	VICTORIA ALL SPORTS		First Name:		
Street:	1902 HOUSTON HIGHWAY 1		City:	VICTORIA	
State:	TX	Zip:	77901	Home Ph:	
Work Ph:	361-575-0655	Product Type:	F	F A T O	
Type Concern:	S	PI PD P S	Concern Code:	1008	
Concern:	FIRED ON BOLT CLOSING				
Cause Code:	4006	Cause:	ALTERED ADJUSTMENTS OR COMPONENTS		
Assigned To:	SUPRY	Classification:	UND	UNJ UNC UND J	
Settlement Detail:	UPDATE UNDER RECALL		Settlement Amount:	\$0.00	
Date Opened Rem:	12/16/2005	Date Opened by P/S:	12/19/2005	Caliber:	222
Date of Incident:		Date Closed:	12/19/2005	Bullet Weight:	
Date to Analysis:		Date from Analysis:		Manufacturer:	REM
Model:	600	Serial:	4139	Date Code:	BL
RAMAC:	600	Litigation:	<input type="checkbox"/>	PreLitigation:	<input type="checkbox"/>
Custody:		Obsolete:	<input checked="" type="checkbox"/>		
Time of Modification:	4:12:51 PM				
Date of Modification:	12/19/2005				
Comments:		TA settings altered - trigger not returning under sear. Non-Remington trigger guard on rifle. Clean action, install new TA, update under recall procedure at n/c.			

(PS 7173)

Serial
Number

4139

Model: 600



RE00105242

Remington

Back to Repair Services

Include it with your firearm

Serial Number: 4139

Are you the original owner?: ☐ YES ☒ NO

Name: Victoria Allsports

Date of Purchase:

Address (no PO Boxes):

1902 Houston Hwy-1

City: Victoria

State: TEXAS

Zip: 77901

Phone (Daytime): 361-575-0650

Fax: 361-575-9543

E-mail Address:

☐ I would like to receive future e-mail updates from Remington.

Please describe your problem and date of occurrence:

Gun fires when closing bolt

Recall Gun
WARRANTY REPAIR

ALTERED ADJUSTMENTS

NEW TA &

Update per recall

Ammunition Information:

Manufacturer:

Type: procedures.

Other (i.e. bullet weight/type, shot size, powder):

FLS 12/19/2005

Handload Information:

Powder Used:

Powder Weight:

Case/Hull Used:

Primer Used:

Bullet Type/Shot Size:

Reloader Used:

Firearms Care (Cleaning and Lubrication):

Brand of cleaning solution used:

How often do you clean the bore? (Months or Number of rounds)

How often do you clean the action? (Months or Number of rounds)

How often do you clean the trigger assembly? (Months or Number of rounds)

http://www.remington.com/support/repair_services/factory_repair_form.... 12/8/2005

DEC 08, 2005 08:42

3365487801

Page 4

(PS 7174)

Date: 12/19/2005

By: FRED SUPRY

FIREARM INSPECTION WORKSHEET

BACKGROUND

Customer name: Victoria All Sports

R.E. Number: 105242

Reason for inspection: 1008 - fire on bolt closing

FIREARM

Manufacturer: REM Model: 600

Serial Number: 4139 Date of Manufacture: BL - 1/64

Overall external condition: good

Barrel condition: ok

Receiver condition: ok

Stock condition: ok

Bolt/firing pin condition: ok

Trigger assembly condition:

Engagement: Trigger not returning under gun

Adjustments/alterations: Altered TA settings

Other: non-Remington Trigger guard

Headspace:

Function evaluation:

File Number:	22063	Arms Service number:	106006
Last Name:	VICK	First Name:	KEITH
Street:	4009 CANTIST	City:	FORT WORTH
State:	TX	Zip:	76116
Home Ph:	817-929-2758	Work Ph:	
Product Type:	F	F A T O	
Type Concern:	S	PI PD P S	Concern Code:
Concern:	FIRED ON SAFE RELEASE		
Cause Code:	4040	Cause:	OTHER - UNSPECIFIED OR UNDETERMINED
Assigned To:	NAGLE	Classification:	UND UNJ UNC UND J
Settlement Detail:	REPLACE TRIGGER N/C	Settlement Amount:	\$0.00
Date Opened Rem:	1/3/2006	Date Opened by P/S:	1/6/2006
Caliber:	6 MM	Bullet Weight:	
Date of Incident:		Date Closed:	1/6/2006
Date to Analysis:		Date from Analysis:	
Manufacturer:	REM	Model:	600
Serial:	72185	Date Code:	PN
Date Mfgd:	6/1/1966	RAMAC:	600
Litigation:	<input type="checkbox"/>	PreLitigation:	<input type="checkbox"/>
Obsolete:	<input checked="" type="checkbox"/>	Custody:	
Comments:	Could not duplicate concern. Trigger has not been updated. Replace TPA, check over completely, and clean action under recall at n/c.		
Time of Modification:	3:47:50 PM	Date of Modification:	1/25/2006

(PS 7177)

Remington Arms Company, Inc.

870 Remington Dr. P.O. Box 700
Madison, NC 27025-0700

Parts/Repairs
Fax

800-243-9700
336-548-7801

www.remington.com info@remington.com

REPAIR DOCUMENT

REPAIR DOCUMENT

Repair Order Number RE00106006 Account # - R-	Description/Serial Number 72185 Model 600 Center Fire Caliber: 6 MM REM	Date Received - 1/6/2006 Estimate Date - Current Date - 1/17/2006
Customer KEITH VICK 4009 CARTIST FORT WORTH, TX 76116 US		Return To KEITH VICK 4009 CARTIST FORT WORTH, TX 76116 US
Phone (H) (817)-929-2758 Phone (W)		Fax Email KEITHVICK@CHARTER.NET

Reported		Found	
M123	FORWARD TO PRODUCT SERVICE FOR INSPECTION	M123	FORWARD TO PRODUCT SERVICE FC
M992	FIRE WHEN PUSHING SAFETY FORWARD	M176	RETURNED FOR RECALL/UPDATE

Technician's Comments	
Condition	LOTS OF SCRATCHES THROUGHOUT/ FIRED OUT OF BATTERY

Parts and Labor		Quantity	Warranty (Y/N)
Material #	Material Description		
Part			
F91469	600 TRIGGER ASSB	1	Y
Part Total:		1	
Service			
4000104	ARMS SERV SHIPPING & HANDLING	0	Y
4000119	GR-TEST	1	Y
4000294	GR-CHECK TPA	1	Y
Service Total:		2	

PS 7178

Remington

Factory Repair Instructions

(NOTE: Please print and complete this form, and then include it with your firearm.)

Model Number: 600		Serial Number: 72185	
Are you the original owner?: <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO		Grandfather bought new (deceased)	
Name: Keith R. Vick		Date of Purchase:	
Address (no PO Boxes): 4009 Cantist			
City: Fort Worth		State: TX	Zip: 76116
Phone (Daytime): 817-929-2758		Fax:	
E-mail Address: keithvick01@charter.net			
<input checked="" type="checkbox"/> I would like to receive future e-mail updates from Remington.			
Please describe your problem:			
Gun jams - sometimes safety won't engage. Last time used, the gun fired when I pushed the safety forward! Gunsmith at shop said to call you about a recall on this gun.			
106006			
Ammunition Information:			
Manufacturer: Remington		Type: 6mm	
Other (i.e. bullet weight/type, shot size, powder):		100 grain	
Handload Information:			
Powder Used:		Powder Weight:	
Case/Hull Used:		Primer Used:	
Bullet Type/Shot Size:		Reloader Used:	
Firearms Care (Cleaning and Lubrication): Invisible Gun			
Brand of cleaning solution used:			
How often do you clean the bore? (Months or Number of rounds) twice/yr			
How often do you clean the action? (Months or Number of rounds)			
How often do you clean the trigger assembly? (Months or Number of rounds)			
Brand of lubricant used: Rem Oil			

Return
Address

Over

PS 7179

How often do you lubricate the bore? (Months or Number of rounds)	<i>twice/yr</i>
How often do you lubricate the action? (Months or Number of rounds)	
How often do you lubricate the trigger assembly? (Months or Number of rounds)	<i>↓</i>
Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual?	
<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO
Comments:	
When was the last time that your firearm was serviced by a Remington authorized repairman/gunsmith?	
What were the services performed? <i>none that I know of</i>	
Ship your INSURED firearm by either UPS or Parcel Post to:	
REMINGTON ARMS CO., INC ATTN: Arms Service Division 14 Hoefler Ave Ilion, NY 13357	
<p>⚠ WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.</p> <p>:: Record the serial number of your firearm before sending it.</p> <p>:: Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.)</p> <p>:: Remove all accessories from your firearm to prevent loss or damage.</p> <p>:: Provide a return address on both the outside and inside the box. Shipments without a proper return address will be refused.</p> <p>:: Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for damage or loss during shipment, so you may elect to purchase insurance from your carrier.</p> <p>Charge repairs will be processed using the following guidelines:</p> <p>:: Repairs \$75.00 and under will be completed and returned to you C.O.D. (To avoid C.O.D. Charges, please include your credit card number and expiration date with your gun)</p> <p>:: For Repairs over \$75.00, you will receive a written estimate detailing the nature of the repair, applicable taxes and shipping. You will have 30 days to approve the repair estimate. Repairs can be paid by check, money order, or credit card (American Express, Discover, MasterCard, or VISA). If you wish, you can expedite repairs over \$75.00 by setting a pre-authorized amount that can be billed to your credit card.</p>	

*could not duplicate concern.
 Trig. has not been updated.
 Replace TPA, checkover, clean
 under recoil AT N/C*

Serial Number:

72185

Model: **600**

PS 7180



RE00106006

Date: 1/6/06

By: B. Travis

FIREARM INSPECTION WORKSHEET

BACKGROUND

Customer name: Keith R. Vick

R.E. Number: 106006

Reason for inspection: FSR

FIREARM

Manufacturer: Rm. Model: 600

Serial Number: 72185 Date of Manufacture: 6/66

Overall external condition: Fair

Barrel condition: OKAY

Receiver condition: OKAY

Stock condition: OKAY

Bolt/firing pin condition: OKAY

Trigger assembly condition:

Engagement: —

Adjustments/alterations: —

Other: OLD style - not updated

Headspace: —

Function evaluation:

Feeding: —

Extraction/ejection: —

Trigger pull: 4*

Manual safety: 01227

Test firing results (if applicable): —

DISPOSITION

could not duplicate concern. Trig. has not been
up dated. Replace TPA, check over, clean AT N/C

ADDITIONAL COMMENTS

File Number:	21993		Arms Service number:	104927	
Last Name:	GULIZIA		First Name:	SEBASTIAN J	
Street:	6927 SOUTH 159TH STREET		City:	OMAHA	
State:	NE	Zip:	68136-3012	Home Ph:	402-861-0421
Work Ph:		Product Type:	F	F A T O	
Type Concern:	S	PI PD P S	Concern Code:	1007	
Concern:	FIRED ON SAFE RELEASE				
Cause Code:	4040	Cause:	OTHER - UNSPECIFIED OR UNDETERMINED		
Assigned To:	NAGLE	Classification:	UND	UNJ UNC UND J	
Settlement Detail:	BLM PROGRAM		Settlement Amount:	\$0.00	
Date Opened Rem:	12/9/2005	Date Opened by P/S:	12/16/2005	Caliber:	308
Date of Incident:		Date Closed:	12/16/2005	Bullet Weight:	
Date to Analysis:		Date from Analysis:		Manufacturer:	REM
Model:	600	Serial:	6224803	Date Code:	PS
Date Mfgd:	6/13/1969				
RAMAC:	600	Litigation:	<input type="checkbox"/>	PreLitigation:	<input type="checkbox"/>
Obsolete:	<input checked="" type="checkbox"/>				
Custody:		Comments:	<p>Could not duplicate concern. Replace TPA, check over completely, clean under Bolt Lock Modification Program for \$20. Repair and Shipping Document 2/20/06.</p>		
Time of Modification:	9:30:31 AM				
Date of Modification:	1/11/2006				

(PS 7183)

Remington.

TRACKING DOCUMENT

Repair Order Number



Repair Order Number RE00104927	Description/Serial Number 6224803	Repairman - Robert Frink Date Received - 12/19/2005
Account # - R-	Model 660 Center Fire Caliber .308 WIN	Estimate Date - 12/19/2005 Current Date - 12/27/2005
Customer SEBASTIAN GULIZIA 6827 SO 159 STREET OMAHA, NE 68136 US	Return To SEBASTIAN GULIZIA 6827 SO 159 STREET OMAHA, NE 68136 US	
Phone (H) (402)-861-0421 Phone (W)	Fax	Email SGULIZIA@COX.NET

Reported Problems		Found	
M992	FIRE WHILE LOADING	M993	SEND TO PRODUCT SERVICE FOR EVALUATION
M993	SEND TO PRODUCT SERVICE FOR EVALUATION		

Material #		Material Desc		Quantity Needed	Quantity From Inv	Quantity From Kit	Warranty (Y/N)
Part							
F91469		600 TRIGGER ASSB		1	1	0	Y
Part Total:				1	1	0	
Service							
4000104		ARMS SERV SHIPPING & HANDLING		0	0	0	Y
4000116		GR-LABOR		20	20	0	N
4000118		GR-CLEAN		1	1	0	Y
4000119		GR-TEST		1	1	0	Y
Service Total:				22	22	0	

Condition	FIRED OUT OF BATTERY				
Problem/Notes	Could not duplicate concern. Replace trigger assembly, check over and clean under Bolt Lock Program.				
Repairman	Proof	Clean	Test	Target	Pattern
Gallery Tester	Date	Date	Date	Date	Date

PS 7184

PLEASE E-MAIL/ME FOR PAYMENT OF
CHARGES AND SHIPPING BACK TO ME, IF
APPLICABLE. DO NOT RETURN COD

3/69

Remington

Factory Repair Instructions

(NOTE: Please print and complete this form, and then include it with your firearm.)

MASTERCARD
5410-0988
EXP. 4/05

REDACTED

Model Number: 660	Serial Number: 6224803
Are you the original owner?: <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	
Name: SEBASTIAN J. GULIZIA	Date of Purchase: 10-20-71
Address (no PO Boxes): 6927 So 159 St	
City: OMAHA	State: NE Zip: 68136-3012
Phone (Daytime): (402) 861-0421	Fax:
E-mail Address: S GULIZIA @ COX .NET	
<input type="checkbox"/> I would like to receive future e-mail updates from Remington.	
Please describe your problem: * SAFETY MODIFICATION PROGRAM * (ALLOW LOADING/UNLOADING SHELLS WITH SAFETY "ON".)	
THIS RIFLE FIRED ON ME WHILE I WAS LOADING SHELLS INTO RIFLE. LUCKILY IT WAS PROPERLY AIMED AT THE GROUND.	
Ammunition Information:	
Manufacturer:	Type:
Other (i.e. bullet weight/type, shot size, powder):	
Handload Information:	
Powder Used:	Powder Weight:
Case/Hull Used:	Primer Used:
Bullet Type/Shot Size:	Reloader Used:
Firearms Care (Cleaning and Lubrication):	
Brand of cleaning solution used:	
How often do you clean the bore? (Months or Number of rounds)	
How often do you clean the action? (Months or Number of rounds)	
How often do you clean the trigger assembly? (Months or Number of rounds)	
Brand of lubricant used:	

could not duplicate concern
replace TPA, check over, clean
under bolt lock program
for \$20.00
quote

Serial Number: 6224803

Model: 660

PS 7185



RE00104927

How often do you lubricate the bore? (Months or Number of rounds)
How often do you lubricate the action? (Months or Number of rounds)
How often do you lubricate the trigger assembly? (Months or Number of rounds)
Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO
Comments: <i>I ONLY USE THE RIFLE FOR A FEW DAYS EACH YEAR DURING DEER SEASON. I CLEAN ENTIRE RIFLE AFTERWARDS.</i>
When was the last time that your firearm was serviced by a Remington authorized repairman/gunsmith? <i>?</i>
What were the services performed? <i>NEW TRIGGER WAS INSTALLED DUE TO A REMINGTON ARMS RECALL OF MODEL 660.</i>
<p>Ship your INSURED firearm by either UPS or Parcel Post to:</p> <p style="text-align: center;">REMINGTON ARMS CO., INC</p> <p style="text-align: center;">ATTN: Arms Service Divison</p> <p style="text-align: center;">14 Hoefler Ave</p> <p style="text-align: center;">Ilion, NY 13357</p>
<p>⚠ WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.</p> <p>:: Record the serial number of your firearm before sending it.</p> <p>:: Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.)</p> <p>:: Remove all accessories from your firearm to prevent loss or damage.</p> <p>:: Provide a return address on both the outside and inside the box. Shipments without a proper return address will be refused.</p> <p>:: Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for damage or loss during shipment, so you may elect to purchase insurance from your carrier.</p> <p>Charge repairs will be processed using the following guidelines:</p> <p>:: Repairs \$75.00 and under will be completed and returned to you C.O.D. (To avoid C.O.D. Charges, please include your credit card number and expiration date with your gun).</p> <p>:: For Repairs over \$75.00, you will receive a written estimate detailing the nature of the repair, applicable taxes and shipping. You will have 30 days to approve the repair estimate. Repairs can be paid by check, money order, or credit card (American Express, Discover, MasterCard, or VISA). If you wish, you can expedite repairs over \$75.00 by setting a pre-authorized amount that can be billed to your credit card.</p>

Date: 12/15/05

By: Bruce Travis

FIREARM INSPECTION WORKSHEET

BACKGROUND

Customer name: Sebastian J. Gwizda

R.E. Number: 104927

Reason for inspection: FBC

FIREARM

Manufacturer: Rum. Model: 660

Serial Number: 6224803 Date of Manufacture: 3/69

Overall external condition: Fair

Barrel condition: OKAY

Receiver condition: OKAY

Stock condition: OKAY

Bolt/firing pin condition: OKAY

Trigger assembly condition:

Engagement: —

Adjustments/alterations: —

Other: DIRTY

Headspace: —

Function evaluation:

File Number:	21860		Arms Service number:	103404	
Last Name:	CLARY		First Name:	CULLEN D.	
Street:	275 BOZMAN ROAD		City:	STONEWALL	
State:	LA	Zip:	71078	Home Ph:	318-925-2421
Work Ph:		Product Type:	F	F A T O	
Type Concern:	S	PI PD P S	Concern Code:	1007	
Concern:	FIRED ON SAFE RELEASE				
Cause Code:	4040	Cause:	OTHER - UNSPECIFIED OR UNDETERMINED		
Assigned To:	NAGLE	Classification:	UND	UNJ UNC UND J	
Settlement Detail:	REPLACE TRIGGER N/C		Settlement Amount:	\$0.00	
Date Opened Rem:	11/14/2005	Date Opened by P/S:	11/15/2005	Caliber:	6 MM
Date of Incident:		Date Closed:	11/14/2005	Bullet Weight:	
Date to Analysis:		Date from Analysis:		Manufacturer:	REM
Model:	600	Serial:	20263	Date Code:	DL
RAMAC:	600	Litigation:	<input type="checkbox"/>	PreLitigation:	<input type="checkbox"/>
Custody:		Obsolete:	<input type="checkbox"/>		
Time of Modification:	2:28:09 PM				
Date of Modification:	12/8/2005				
Comments:	Trigger assembly has not been updated from recall. Replace TPA, check over and clean action at n/c - charge 230145.				

(PS 7189)

9/64

103404

Remington.

Repair Form

(NOTE: Please print and complete this form, and then include it with your firearm.)

Model Number: 600		Serial Number: 20263	
Name: Cullen D. Clary		Date of Purchase: 1989	
Address (no PO Boxes): 275 Bozman Rd.			
City: Stonewall		State: La	Zip: 71078
Phone (Daytime): 318-925-2421		Fax:	
E-mail Address: Cell phone 318-470-0027			
Please describe your problem: you cannot load or unload this rifle if safety is on.			
This rifle also goes discharges when bloting action, it just sometimes goes off. please repair			
Additional Information: (Ammo type, brand, handload specifications, etc.)			
I bought this rifle used from a pawn shop for my young son. I did not know about the recalls.			
NOTE: Prior to shipping your firearm, contact the Repair Center for services provided and estimated repair time.			
<p>WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.</p>			

Please repair ASAP.

Thanks

TRIP ASSM. HAS NOT BEEN updated from Rev 11. Replace TPA check over, clean action AT N/C #230145

Serial Number: 20263
Model: 600
PS 7190
RE00103404

Date: 11/14/05

By: Bruce TIRAOIS

FIREARM INSPECTION WORKSHEET

BACKGROUND

Customer name: Cullen D. Clary

R.E. Number: 103404

Reason for inspection: F.B.C.

FIREARM

Manufacturer: Rum. Model: 600

Serial Number: 20263 Date of Manufacture: 9/64

Overall external condition: Fair

Barrel condition: OKAY

Receiver condition: OKAY

Stock condition: OKAY

Bolt/firing pin condition: OKAY

Trigger assembly condition:

Engagement: —

Adjustments/alterations: —

Other: Dirty

Headspace: —

Function evaluation:

File Number:	21871		Arms Service number:		
Last Name:	ALDERMAN		First Name:	ALAN & LOGAN	
Street:	1001 GLENDALE ROAD		City:	GALAX	
State:	VA	Zip:	24333	Home Ph:	276-238-1481
Work Ph:		Product Type:	F	F A T O	
Type Concern:	PI	PI PD P S	Concern Code:	1025	
Concern:	UNEXPLAINED DISCHARGE - FOOT				
Cause Code:	4040	Cause:	OTHER - UNEXAMINED		
Assigned To:	SUPRY	Classification:	UND	UNJ UNC UND J	
Settlement Detail:		Settlement Amount:	\$0.00		
Date Opened Rem:		Date Opened by P/S:	12/5/2005	Caliber:	243
Date of Incident:		Date Closed:		Bullet Weight:	
Date to Analysis:		Date from Analysis:		Manufacturer:	REM
Model:	600	Serial:	43378	Date Code:	
RAMAC:	600	Litigation:	<input type="checkbox"/>	PreLitigation:	<input checked="" type="checkbox"/>
Custody:		Obsolete:	<input type="checkbox"/>		
Time of Modification:	8:06:50 AM				
Date of Modification:	12/13/2005				
Comments:		12 year old Logan, had an accidental discharge of the firearm. Shooting his big toe off. It has been reattached, but unknown if it will take. Model 600 rifle was taken by the Fish & Game authorities. His father, Alan, will send the gun in once he gets it back. ARS label and letter sent 12/7/05. Medical bills are taken care of.			

[PS 7193]

UPS DRIVER INSTRUCTIONS: YOU ARE AUTHORIZED TO ACCEPT THIS PACKAGE WITHOUT A PICKUP RECORD.

Name: ALAN ALDERMAN

Company: _____

Street: 1001 Blendale Road

City: GALAX State: VA ZIP Code: 24333

REF #: _____


A.R.S.

PD

T O
FED SUPPLY
REMINGTON ARMS
14 HOEFLER AVE
ILION NY 13357

 **UPS Next Day Air** **1**
EXTREMELY URGENT

TRACKING NUMBER



1Z E13 390 27 5000 1673

UPS Authorized Return Service™

01118011

UPS Louisville, KY 297 W



Next Day Air A.R.S. Tracking Number

REF #/DATE

1Z E13 390 27 5000 167 3



07 December 2005

Alan Alderman
1001 Glendale Road
Galax, VA 24333

RE: Firearm Accident
Personal Injury

Dear Alan,

We were sorry to learn of the unfortunate incident that Logan experienced while enjoying a day of hunting. We certainly hope that the reattachment of his big toe works and that he has a speedy recovery. We were impressed that he is still anxious to be out enjoying the shooting sports. It is people like Logan that will be the future for all the firearms and ammunition companies.

As we discussed, I have enclosed an ARS label for you to return the rifle, once you get it back from the fish & game authorities, to my attention for examination and repair/updating as needed. When we have completed our examination we will contact you with our findings. Please put a copy of this letter inside the shipping box when you return the rifle. The letter inside is important as sometimes the outside label gets damaged in transit and we want to be sure the rifle is logged in correctly.

We understand that this was Logan's grandfather's rifle and it will have great sentimental value to him, so if it can be repaired and safe to have in the field we will do that at no charge. We apologize for the inconvenience that this incident has caused, but, look forward to being of service. If you have any questions feel free to contact me directly.

Sincerely,

Fred Supry, Manager
Product Service and Law Enforcement Training
Remington Arms Company
14 Hoefler Avenue
Ilion, NY 13357

Phone: 315-895-3606
E-mail: fred.supry@remington.com

Remington Arms Company, Inc. • 14 Hoefler Avenue • Ilion, NY 13357
Phone 315-895-3200 • www.remington.com

(PS 7195)

File Number:	21919	Arms Service number:	104916
Last Name:	ADAMS	First Name:	JACK C
Street:	4235 SOMERSET DRIVE NORTHEAST	City:	ALBANY
State:	OR	Zip:	97322
Work Ph:		Home Ph:	541-760-8631
Product Type:	F	F A T O	
Type Concern:	S	PI PD P S	
Concern Code:	1007		
Concern:	FIRED ON SAFE RELEASE		
Cause Code:	4006	Cause:	ALTERED ADJUSTMENTS OR COMPONENTS
Assigned To:	SUPRY	Classification:	UND UNJ UNC UND J
Settlement Detail:	UPDATE UNDER RECALL		Settlement Amount:
Date Opened Rem:	12/15/2005	Date Opened by P/S:	12/15/2005
Date of Incident:		Date Closed:	12/16/2005
Date to Analysis:		Date from Analysis:	
Model:	600	Serial:	57918
RAMAC:	600	Date Code:	BN
Custody:		Date Mfgd:	1/3/1966
Time of Modification:	10:05:52 AM	Litigation:	<input type="checkbox"/>
Date of Modification:	12/19/2005	PreLitigation:	<input type="checkbox"/>
		Obsolete:	<input checked="" type="checkbox"/>
Comments: Could not duplicate concern. Trigger settings altered. Rifle never updated. Clean action, install new TA - update-under recall. Repair and Shipping Document 2/20/06.			

(PS 7196)

Remington.

TRACKING DOCUMENT

Repair Order Number



Repair Order Number

RE00104916

Description/Serial Number

57918

Repairman - Dale Lewis

Date Received - 12/15/2005

Account # - R-

Model 600 Center Fire Caliber: 308 WIN

Estimate Date -

Current Date - 12/20/2005

Customer

JACK ADAMS

4235 SOMERSET DRIVE NORTH EAST

ALBANY, OR 97322 US

Return To

JACK ADAMS

4235 SOMERSET DRIVE NORTH EAST

ALBANY, OR 97322 US

Phone (H) (541)-760-8631

Fax

Phone (W)

Email JCADAMS@COMCAS

Problems

Reported

M123

FORWARD TO PRODUCT SERVICE
FOR INSPECTION
M993 FIRED WHEN SAFETY WAS
RELEASED

M123

FORWARD TO PRODUCT SERVICE F

Repair

Material #	MaterialDesc	Quantity Needed	Quantity From Inv	Quantity From Kit	Warranty (Y/N)
Part					
F91469	600 TRIGGER ASSB	1	1	0	Y
Part Total:		1	1	0	
Service					
4000104	ARMS SERV SHIPPING & HANDLING	0	0	0	Y
4000119	GR-TEST	1	1	0	Y
4000294	GR-CHECK TPA	1	1	0	Y
Service Total:		2	2	0	

Condition

FIRED OUT OF BATTERY

ProblemNotes

could not duplicate concern, trig set screws altered, old style trig assem, replace tpa under recall at n/c per prod service

Repairman	Proof	Clean	Test	Target	Pattern
Gallery Tester	Date	Date	Date	Date	Date

PS 7197

1/66 5

Remington

General Repair Form

(NOTE: Please print and complete this form, and then include it with your firearm.)

Model Number: 600		Serial Number:	
Name: ADAMS, JACK C.		Date of Purchase: 1965	
Address (no PO Boxes): 4235 SOMERSET DR. NE			
City: ALBANY		State: OREGON	Zip: 97322
Phone (Daytime): (541) 760-8631		Fax:	
E-mail Address: jcadams@comcast.net			
Please describe your problem:			
FIREARM FIRED WHEN SAFETY WAS RELEASED			
Additional Information: (Ammo type, brand, handload specifications, etc.)			
PS. THIS GUN HAS BEEN IN MY FAMILY AS LONG			
AS I CAN REMEMBER. I THINK MY FATHER			
BOUGHT IT IN 1965.			
NOTE: Prior to shipping your firearm, contact the Repair Center for services provided and estimated repair time.			
<p>Ⓢ WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.</p> <p>Ⓢ Record the serial number of your firearm before sending it.</p> <p>Ⓢ Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.)</p> <p>Ⓢ Remove all accessories from your firearm to prevent loss or damage.</p> <p>Ⓢ Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for damage or loss during shipment, so you may elect to purchase insurance from your carrier.</p>			

would not duplicate concern
 TRIG-sets screw & altered
 MOD STYLE TRIG. ASSM.
 replace TRA under recall.
 AT N/C

104916

Serial Number:

57918

Model: 600

PS 7198



RE00104916

Remington.

Repair Form

(NOTE: Please print and complete this form, and then include it with your firearm.)

Model Number: 600	Serial Number: 57918	
Name: Jack C. Adams	Date of Purchase: 1966	
Address (no PO Boxes): 545 S. 14 th Street		
City: Lebanon	State: Oregon	Zip: 97355
Phone (Daytime): (541) 760-8631	Fax:	
E-mail Address: jack-adams@comcast.net		
Please describe your problem: This gun was originally purchased by my father. I own it now, and was sighting it in, reloading for another string, the gun fired into the target after releasing the safety. I had a local gunsmith repair it, but later the gun again unexpectedly fired, nearly shooting myself in the foot.		
Additional Information: (Ammo type, brand, hand load specifications, etc.)		
1. Would it be possible for your custom shop to shoot some test patterns to give me some insight on what level of accuracy to expect from this gun. And what load shoots best?		
2. If so, would there be a charge for this service?		
NOTE: Prior to shipping your firearm, contact the Repair Center for services		

Remington.

Repair Form

(NOTE: Please print and complete this form, and then include it with your firearm.)

Model Number: 600	Serial Number: 57918	
Name: Jack C. Adams	Date of Purchase: 1966	
Address (no PO Boxes): 545 S. 14 th Street		
City: Lebanon	State: Oregon	Zip: 97355
Phone (Daytime): (541) 760-8631	Fax:	
E-mail Address: jack-adams@comcast.net		
Please describe your problem: This gun was originally purchased by my father. I own it now, and was sighting it in, reloading for another string, the gun fired into the target after releasing the safety. I had a local gunsmith repair it, but later the gun again unexpectedly fired, nearly shooting myself in the foot.		
Additional Information: (Ammo type, brand, hand load specifications, etc.)		
1. Would it be possible for your custom shop to shoot some test patterns to give me some insight on what level of accuracy to expect from this gun. And what load shoots best?		
2. If so, would there be a charge for this service?		
NOTE: Prior to shipping your firearm, contact the Repair Center for services		

PS 7200

How to participate in the Safety Modification Program:

1. Complete the General Repair Form and
2. Send or deliver your firearm and the completed repair form to either:
 - a) A Remington Authorized Repair Center; or
 - b) Ship your firearm to the Remington factory at:

Remington Arms Company, Inc.
Ilion Firearms Plant
Attention: BL Safety Program
14 Hoefler Avenue
Ilion, NY 13357

History 1 800 243-9700 M-F 9-5 EST

OREGON

Pisco, Inc.

1455 B North Hemlock St.
Coquille, OR 97423
Phone: 541-396-5558
Fax: 541-396-2347

Allison & Carey Gun Works, Inc.

17311 SE Stark
Portland, OR 97233
Phone: 503-256-5166

Custom Gunsmith

1033 Elizabeth St.
Eugene, OR 97402
Phone: 541-689-1687

Date: 12/15/05

By: Bruce Travis

FIREARM INSPECTION WORKSHEET

BACKGROUND

Customer name: JACK C. ADAMS

R.E. Number: 104916

Reason for inspection: FSR

FIREARM

Manufacturer: Rum Model: 600

Serial Number: 57918 Date of Manufacture: 1/66

Overall external condition: FAIR

Barrel condition: OKAY

Receiver condition: OKAY

Stock condition: OKAY

Bolt/firing pin condition: OKAY

Trigger assembly condition:

Engagement: ALTERED

Adjustments/alterations: ALTERED

Other: —

Headspace: 2

Function evaluation:

Feeding: _____

Extraction/ejection: _____

Trigger pull: 3rd _____

Manual safety: DICKEY-BOUL COCK _____

Test firing results (if applicable): _____

DISPOSITION

could not duplicate concern. Trigger set screws altered.
OLD STYLE TPA, replace TPA under recall.

ADDITIONAL COMMENTS

AT N/C