

Remington Arms Co., Inc.  
Product Service  
Legal Case #:640

## Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
120244	11/20/2006	11/21/2006	11/21/2006				X

## Customer Information

Type	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	Linus	Leppinic	5155 E Davies Dr.	Centennial	CO	80122		H 303-773-2034

## Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD				
S	Cause:4038	Could Not Duplicate Concern	Unknown	
C	fires on bolt closing	Concern:1020 Fired on Bolt Opening		

11/21/06-correspondence from repair-the firearm discharges when a round is placed in the chamber as bolt is closed. Cust checked this with spent case.lw

## Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	660/243		6236086	XS	12/1/1969
Date Purchased	Where Purchased	Accessories	Original Owner			
		Scope base	U			

Ammunition Information - None Defined

Other Products Information - None Defined

## Settlement

Remington/660/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Replace TA at n/c under recall						

Repair/Replacement Cost	Repair/Replacement Date
\$25.00	11/21/2006

1/21/06-replaced trigger at n/c under recall.lw

Examination[Remington/CF/BA]

PS 7205

Part	Sub-Part	Code	Comment
Examination	Examiner		Supry
	Exam Date		11/21/2006
	Product Type		RF
	Action Type		A
	Assigned To		Supry
Cause	4015	Improper Maintenance	
Barrel	Description		20 inch 243 caliber 660
	Date Code		XS
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Worn; Functioning	
	Face	Slightly Worn; Functioning	lots of brass shavings on bolt face
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	Some sticky residue visible on bolt stop.
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Magazine	Condition	---Select---	
	Box Condition	Slightly Worn; Functioning	
Overall	Exterior Condition	Worn; Functioning	
	Stock Condition	Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	

( PS 7206 )

	Bulged	False	
Safety	Description		Bolt lock safetu
	Function	Slightly Worn; Functioning	
Sear	Lift	---Select---	
	Notch	---Select---	
Trigger	Condition	Abused; Functioning	Sear movement sluggish due to sticky residue build up in TA.
	Pull	---Select---	3.5
	Altered	False	

( PS 7207 )

Status: Inspected 11/28/2006 1:23:55 PM

## FFL:

**Close**

Serial  
Number:

6236086

Model: 660



RE00120244



Linus Leppink  
5155 E Davies Dr  
Centennial CO  
80122  
303-773-2034

this firearm discharges  
when a round is placed  
in the chamber; as  
bolt is closed.  
I checked this with  
ammo with powder  
removed.

STICKY RESIDUE IN TRIGGER ASSEMBLY  
COULD NOT  
DUPLICATE CONCERN  
BOLT LOCK SAFETY  
UPDATE PER CURRENT  
PROCEDURES NR  
FLS 11/21/2006

120244

#640

Mr. and Mrs. Linus Leppink

C15758

PS 7209

File Number:	22116	Arms Service number:	107751
Last Name:	SAXION	First Name:	MIKE
Street:	5131 FM 2493 EAST	City:	BULLARD
State:	TX	Zip:	75757
Home Ph:	903-571-5251		
Work Ph:		Product Type:	F F A T O
Type Concern:	S	PI PD P S	
Concern Code:	1007		
Concern:	FIRED ON SAFE RELEASE		
Cause Code:	4006	Cause:	ALTERED ADJUSTMENTS OR COMPONENTS
Assigned To:	SUPRY	Classification:	UND UNJ UNC UND J
Settlement Detail:	BLM PROGRAM	Settlement Amount:	\$0.00
Date Opened Rem:	2/6/2006	Date Opened by P/S:	2/6/2006
Caliber:	308		
Date of Incident:		Date Closed:	2/7/2006
Bullet Weight:			
Date to Analysis:		Date from Analysis:	
Manufacturer:	REM		
Model:	660	Serial:	111589
Date Code:	CR	Date Mfgd:	4/1/1968
RAMAC:	660	Litigation:	<input type="checkbox"/>
PreLitigation:	<input type="checkbox"/>	Obsolete:	<input checked="" type="checkbox"/>
Custody:		Comments:	TA set screws altered. Clean action, install new TA \$20 under the Bolt Lock Modification Program. Repair and Shipping Document 2/20/06.
Time of Modification:	7:56:22 AM		
Date of Modification:	2/10/2006		

PS 7210

# Remington Arms Company, Inc.

870 Remington Dr. P.O. Box 700

Madison, NC 27025-0700

Parts/Repairs

800-243-9700

Fax

336-548-7801

[www.remington.com](http://www.remington.com) [info@remington.com](mailto:info@remington.com)

## REPAIR DOCUMENT

## REPAIR DOCUMENT

Repair Order Number RE00107751 Account # - R-	Description/Serial Number 111589 Model 660 Center Fire Caliber: 308 WIN	Date Received - 2/6/2006 Estimate Date - Current Date - 2/8/2006
Customer MIKE SAXION 5131 8M 2493 CAST  BULLARD. TX 75757 US	Return To MIKE SAXION 5131 8M 2493 CAST  BULLARD. TX 75757 US	
Phone (H) (903)-571-5251 Phone (W)	Fax Email DONALDMS00@EARTHLINK.NI	

Reported:	Problems	Found:
M110 FAILS TO FIRE M992 DISCHARGES WHEN TRIGGER IS NOT TOUCHED M993 SEND TO PRODUCT SERVICE FOR EVALUATION	M239	REPLACE TRIGGER ASSEMBLY

Technician's Comments
ProblemNotes Had the old style trigger assem. Replaced trigger assem. under the recall.

Parts and Labor		Quantity	Warranty (Y/N)
Material #	Material Description		
Part			
F91469	600 TRIGGER ASSB	1	Y
Part Total:		1	
Service			
4000104	ARMS SERV SHIPPING & HANDLING	0	Y
4000119	GR-TEST	1	Y
4000294	GR-CHECK TPA	1	Y
Service Total:		2	

PS 7211

2.54

4/68

# Remington.

## Factory Repair Instructions

(NOTE: Please print and complete this form, and then include it with your firearm.)

Model Number: 660		Serial Number: 111589	
Are you the original owner?: <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO			
Name: Mike Saxion		Date of Purchase: <del>2000</del> 1968	
Address (no PO Boxes): 5131 FM 2493 east			
City: Ballard		State: TX	Zip: 75757
Phone (Daytime): 903 571-5251		Fax:	
E-mail Address: <input type="checkbox"/> DonaldMS00@earthlink.net I would like to receive future e-mail updates from Remington.			
Please describe your problem:			
<p>The firing pin will not "set"/engage when the bolt is cycled. Sometimes the pin will set when the safety is on while cycling the bolt. However, when the safety is pushed off the rifle <del>will</del> will fire. The rifle will discharge when the trigger is not pushed.</p> <p><del>EVERY DANGEROUS</del></p>			
Ammunition Information:			
Manufacturer: Federal		Type: MISC	
Other (i.e. bullet weight/type, shot size, powder):			

passed down in family

\*

Serial Number:

Information: N/A

Powder Weight:

Primer Used:

Shot Size:

Reloader Used:

(Cleaning and Lubrication):

Cleaning solution used: Sharps choice

How often do you clean the bore? (Months or Number of rounds) 10 rounds

How often do you clean the action? (Months or Number of rounds) 30 rounds

How often do you clean the trigger assembly? (Months or Number of rounds) 1 per year

Grease used: Rem tech

TRIG-ASSM. set screws altered.  
replace TPA, check over, clean under  
Bolt Lock program for \$20.00

Quote ( PS 7212 )



Model: 660

111589

How often do you lubricate the bore? (Months or Number of rounds)	1/ month
How often do you lubricate the action? (Months or Number of rounds)	1/ month
How often do you lubricate the trigger assembly? (Months or Number of rounds)	
Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual?	
<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO
Comments:	
When was the last time that your firearm was serviced by a Remington authorized repairman/gunsmith? ?	
What were the services performed?	
Ship your <b>INSURED</b> firearm by either <b>UPS</b> or <b>Parcel Post</b> to:	
<b>REMINGTON ARMS CO., INC</b>  <b>ATTN: Arms Service Division</b> <b>14 Hoefler Ave</b> <b>Ilion, NY 13357</b>	
<p><b>⚠ WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.</b></p> <p>             :: Record the serial number of your firearm before sending it.              :: Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.)              :: Remove all accessories from your firearm to prevent loss or damage.              :: Provide a return address on both the outside and inside the box. Shipments without a proper return address will be refused.              :: Ship your <b>INSURED</b> firearm by either <b>UPS</b> or <b>Parcel Post</b>. Remington is not responsible for damage or loss during shipment, so you may elect to purchase insurance from your carrier.         </p> <p>Charge repairs will be processed using the following guidelines:</p> <p>             :: Repairs \$75.00 and under will be completed and returned to you C.O.D. (To avoid C.O.D. Charges, please include your credit card number and expiration date with your gun)               :: For Repairs over \$75.00, you will receive a written estimate detailing the nature of the repair, applicable taxes and shipping. You will have 30 days to approve the repair estimate. Repairs can be paid by check, money order, or credit card (American Express, Discover, MasterCard, or VISA). If you wish, you can expedite repairs over \$75.00 by setting a pre-authorized amount that can be billed to your credit card.         </p>	

Date: 2/7/06

By: B. TRAUIS

**FIREARM INSPECTION WORKSHEET**

**BACKGROUND**

Customer name: MIKE SAXION

R.E. Number: 107751

Reason for inspection: FSR

**FIREARM**

Manufacturer: Rum Model: 660

Serial Number: 111589 Date of Manufacture: 4/68

Overall external condition: FAIR

Barrel condition: OKAY

Receiver condition: OKAY

Stock condition: OKAY

Bolt/firing pin condition: OKAY

Trigger assembly condition:

Engagement: ALTERED

Adjustments/alterations: ALTERED

Other: —

Headspace: —

Function evaluation:

Feeding: \_\_\_\_\_

Extraction/ejection: \_\_\_\_\_

Trigger pull: 2.5<sup>4</sup>

Manual safety: 01/14/4 - BOCTLOCK

Test firing results (if applicable): \_\_\_\_\_

DISPOSITION

TRIG. ASSM. SET SCREWS ADJUSTED. REPLACE TPA,  
CHECK OVER, CLEAN UNDER BOLT LOCK PROGRAMMER \$20.00

ADDITIONAL COMMENTS

Quote

File Number:	22120		Arms Service number:	107842	
Last Name:	FRIEL		First Name:	PETER	
Street:	7 MANSEWOOD ROAD		City:	OLD LYME	
State:	CT	Zip:	06371	Home Ph:	
Work Ph:	203-488-8994		Product Type:	F	F A T O
Type Concern:	S	PI PD P S	Concern Code:	1008	
Concern:	FIRED ON BOLT CLOSING				
Cause Code:	4006	Cause:	ALTERED ADJUSTMENTS OR COMPONENTS		
Assigned To:	SUPRY	Classification:	UND	UNJ UNC UND J	
Settlement Detail:	UPDATE PER CURRENT PROCEDURES			Settlement Amount:	\$0.00
Date Opened Rem:	2/7/2006	Date Opened by P/S:	2/7/2006	Caliber:	243
Date of Incident:		Date Closed:	2/7/2006	Bullet Weight:	
Date to Analysis:		Date from Analysis:		Manufacturer:	REM
Model:	660	Serial:	110241	Date Code:	CR
Date Mfgd:	4/1/1968				
RAMAC:	660	Litigation:	<input type="checkbox"/>	PreLitigation:	<input type="checkbox"/>
		Obsolete:	<input checked="" type="checkbox"/>		
Custody:		Comments:	Firearm never updated - update per current procedures at n/c. As received the set screw positions were altered. Repair and Shipping Document 2/20/06.		
Time of Modification:	8:11:27 AM				
Date of Modification:	2/10/2006				

PS 7216

# Remington.

## TRACKING DOCUMENT

Repair Order Number



Repair Order Number

RE00107842

Account # - R-

Description/Serial Number

110241

Model 660 Center Fire Caliber 243 WIN

Repairman - Herb Brown

Date Received - 2/7/2006

Estimate Date -

Current Date - 2/8/2006

Customer

PETER FRIEL

7 MANSEWOOD ROAD

OLD LYME, CT 06371 US

Return To

PETER FRIEL

7 MANSEWOOD ROAD

OLD LYME, CT 06371 US

Phone (H) (203)-488-8774

Phone (W)

Fax (203)-488-0359

Email PFRIEL@OUTDRS.NE

### Problems

#### Reported

M992 FIRED WITHOUT TOUCHING  
TRIGGER  
M993 SEND TO PRODUCT SERVICE FOR  
EVALUATION

#### Found

M176 RETURNED FOR RECALL/UPDATE  
M993 SEND TO PRODUCT SERVICE FOR E

### Repair

Material # MaterialDesc

Quantity  
Needed

Quantity  
From Inv

Quantity  
From Kit

Warranty  
(Y/N)

#### Part

F91469 600 TRIGGER ASSB

Part Total:

#### Service

4000104 ARMS SERV SHIPPING & HANDLING

4000119 GR-TEST

Service Total:

ProblemNotes up date done 2/7/06

Repairman	Proof	Clean	Test	Target	Pattern
Gallery Tester	Date	Date	Date	Date	Date

PS 7217

10784 Remington

# Factory Repair Form

Return to Previous Page

NOTE: Please print and complete this form, and then include it with your firearm

Model Number: 660 (243)		Serial Number: 110241	
Are you the original owner?: <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO			
Name: PETER FRIEL		Date of Purchase: 1990	
Address (no PO Boxes):			
7 MANSEWOOD ROAD			
City: OLD LYME		State: CT	Zip: 06371
Phone (Daytime): 203.488.8994		Fax: 203.488.0359	
E-mail Address:			
<input type="checkbox"/> I would like to receive future e-mail updates from Remington. PFRIEL@OUTDOORS.NET			
Please describe your problem and date of occurrence: I BOUGHT THIS GUN IN 1990 FROM AN OLD TIMER WHO WAS SELLING OFF HIS GUNS. I NEVER FIRED THIS GUN UNTIL LAST FALL AND FOUND OUT THAT IT HAD A FAULTY TRIGGER AND SAFETY MECHANISM. AT FIRST IT HAD A DELAYED FIRE AFTER PULLING THE TRIGGER THEN IT FIRED AFTER CLOSING THE BOLT WITHOUT EVER TOUCHING THE TRIGGER. IF THE TRIGGER SYSTEM IS WHATS AT FAULT AND IT CAN BE REPAIRED IS IT THEN POSSIBLE TO ADJUST THE TRIGGER TO A 3# PULL? IF THIS CAN BE DONE			
Ammunition Information: FOR UNDER \$100.00 THEN PLEASE PROCEED WITH THE WORK			
Manufacturer:		Type:	
Other (i.e. bullet weight/type, shot size, powder):			
* CREDIT CARD INFO: VISA EXP. 12/07			
Handed Information: # 4264 2901		REDACTED PETER FRIEL	
Powder Used:		Powder Weight:	
Case/Hull Used:		Primer Used:	
Bullet Type/Shot Size:		Reloader Used:	

THANK YOU VERY MUCH

PETER FRIEL

Serial Number:

110241

Model: 660



RE00107842

TRIG. ASSM. SET SCREWS ALTERED.

Replace TPA, check over, clean under barrel

number of rounds) SET TRIG. pull to min spec.

months or Number of rounds) H/C

factory\_repair\_form.asp

1/29/2006

PS 7218

Brand of lubricant used:

How often do you lubricate the bore? (Months or Number of rounds)

How often do you lubricate the action? (Months or Number of rounds)

How often do you lubricate the trigger assembly? (Months or Number of rounds)

Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual? ☐ YES ☐ NO

Comments:

When was the last time that your firearm was serviced by a Remington authorized repairman/gunsmith? *NEVER WHILE IN MY POSSESSION*

What were the services performed?

\* RETURN ADDRESS

Ship your INSURED firearm by either UPS or Parcel Post to:

Remington Arms Co., Inc.  
Attn: Arms Service Division  
14 Hoefler Avenue  
Ilion, NY 13357

PETER FRIEL  
17 MANSEWOOD ROAD  
OLD LYME, CT 06371  
(HOME PHONE 860-434-1811)

**Ⓢ WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.**

- :: Record the serial number of your firearm before sending it.
- :: Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.)
- :: Remove all accessories from your firearm to prevent loss or damage.
- :: Provide a return address on both the outside and inside the box. Shipments without a proper return address will be refused.
- :: Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for damage or loss during shipment, so you may elect to purchase insurance from your carrier.

Charge repairs will be processed using the following guidelines:

:: Repairs \$75.00 and under will be completed and returned to you C.O.D. (To avoid C.O.D. Charges, please include your credit card number and expiration date with your gun)

:: For Repairs over \$75.00, you will receive a written estimate detailing the nature of the repair, applicable taxes and shipping. You will have 30 days to approve the repair estimate. Repairs can be paid by check, money order, or credit card (American Express, Discover, MasterCard, or VISA). If you wish, you can expedite repairs over \$75.00 by setting a pre-authorized amount that can be billed to your credit card.

Date: 2/7/06

By: B. T. MAVIN

**FIREARM INSPECTION WORKSHEET**

**BACKGROUND**

Customer name: Peter Friel

R.E. Number: 107842

Reason for inspection: Delay FIED - FDC

**FIREARM**

Manufacturer: Rm. Model: 660

Serial Number: 110241 Date of Manufacture: 4/68

Overall external condition: FAIR

Barrel condition: OKAY

Receiver condition: OKAY

Stock condition: OKAY

Bolt/firing pin condition: OKAY

Trigger assembly condition:

Engagement: ALTERED

Adjustments/alterations: ALTERED

Other: —

Headspace: —

Function evaluation:



File Number:	21969		Arms Service number:	105430	
Last Name:	BRYANT		First Name:	JIMMIE	
Street:	PO BOX 1224		City:	LENOIR	
State:	NC	Zip:	28645	Home Ph:	828-758-2023
Work Ph:		Product Type:	F	F A T O	
Type Concern:	S	PI PD P S	Concern Code:	1007	
Concern:	FIRED ON SAFE RELEASE				
Cause Code:	4006	Cause:	ALTERED ADJUSTMENTS OR COMPONENTS		
Assigned To:	SUPRY	Classification:	UND	UNJ UNC UND J	
Settlement Detail:	UPDATE N/C		Settlement Amount:	\$0.00	
Date Opened Rem:	12/29/2005	Date Opened by P/S:	12/29/2005	Caliber:	308
Date of Incident:		Date Closed:	12/29/2005	Bullet Weight:	
Date to Analysis:		Date from Analysis:		Manufacturer:	REM
Model:	660	Serial:	6224418	Date Code:	PS
Date Mfgd:	6/13/1969				
RAMAC:	660	Litigation:	<input type="checkbox"/>	PreLitigation:	<input type="checkbox"/>
Obsolete:	<input checked="" type="checkbox"/>				
Custody:		Comments:	TA screws positions altered. TA never updated. Update per current procedures at n/c. Repair and Shipping Document 2/20/06.		
Time of Modification:	10:01:06 AM				
Date of Modification:	1/10/2006				

( PS 7222 )

# Remington Arms Company, Inc.

870 Remington Dr. P.O. Box 700

Madison, NC 27025-0700

Parts/Repairs

800-243-9700

Fax

336-548-7801

[www.remington.com](http://www.remington.com) [info@remington.com](mailto:info@remington.com)

## REPAIR DOCUMENT

## REPAIR DOCUMENT

<b>Repair Order Number</b> RE00105430 <b>Account # - R-</b>	<b>Description/Serial Number</b> 6224418 Model 660 Center Fire Caliber: 308 WIN	<b>Date Received -</b> 12/29/2005 <b>Estimate Date -</b> ✓ <b>Current Date -</b> 1/4/2006
<b>Customer</b> JIMMIE BRYANT  P.O. BOX 1224 LENOIR, NC 28645 US	<b>Return To</b> GARYS GUNSMITHING 5366 STATE ROUTE 31  VERONA, NY 13478 US	
<b>Phone (H)</b> (828)-758-2023 <b>Phone (W)</b>	<b>Fax</b> <b>Email</b>	

Problems	
Reported:	Found:
M123 FORWARD TO PRODUCT SERVICE FOR INSPECTION	M123 FORWARD TO PRODUCT SERVICE FC
M239 REPLACE TRIGGER ASSEMBLY	
M992 FIRES WHEN TAKEN OFF SAFE	

Technician's Comments	
ProblemNotes	trigger set screws altered. trigger has not been updated. replace trigger plate assm under recall, check over, clean at no charge.

Parts and Labor			
Material #	Material Description	Quantity	Warranty (Y/N)
<b>Part</b>			
F91469	600 TRIGGER ASSB	1	Y
<b>Part Total:</b>		1	
<b>Service</b>			
4000104	ARMS SERV SHIPPING & HANDLING	0	Y
4000119	GR-TEST	1	Y
<b>Service Total:</b>		1	

PS 7223

Dec 12, 2005

Trig. setscrews altered.  
Trig. has not been updated.  
Replace TPA under recall, check  
over, clean at N/C

3# 3/69

Dear Sir,

Enclosed is a Remington Model 660.  
The safety needs to be repaired or replaced.  
The rifle will fire when the safety  
is taken off without touching the  
trigger. There was a recall on this model  
some time ago. However, we have not  
experienced any problems until  
recently.

If there is a charge, please let me  
know.


Thank you,

W 5430

Jimmie Bryant  
PO Box 1224  
Lenoir, NC 28645  
828-758-2023

Serial Number: 6224418

Model: 660



RE00105430

( PS 7224 )

Date: 12/29/05

By: B. TRAVIS

FIREARM INSPECTION WORKSHEET

BACKGROUND

Customer name: Jimmie BRYANT

R.E. Number: 105430

Reason for inspection: FSR

FIREARM

Manufacturer: Rum. Model: 660

Serial Number: 6224418 Date of Manufacture: 3/69

Overall external condition: FAIR

Barrel condition: OKAY

Receiver condition: OKAY

Stock condition: OKAY

Bolt/firing pin condition: OKAY

Trigger assembly condition:

Engagement: ALTERED

Adjustments/alterations: ALTERED

Other: OLD STYLE - NOT updated

Headspace: -

Function evaluation:

