

Remington Arms Co., Inc.
Product Service
Legal Case #:976

Case Information

| RE# | Date Opened | Date Opened(PS) | Date Closed | Incident Date | Pre Lit | Lit | Obsolete |
|--------|-------------|-----------------|-------------|---------------|---------|-----|----------|
| 124546 | 1/31/2007 | 1/31/2007 | 1/31/2007 | | | | |

Customer Information

| Type | First Name | Last Name | Street | City | State | Zip | Age | Contact |
|----------|------------|----------------|----------------|------------|-------|-------|-----|----------------|
| Reporter | | Bass Pro Shops | 3501 Paxton St | Harrisburg | PA | 17111 | | W 717-565-5261 |

Incident Information

| Claims | Codes | Repair Est. | Medical Treatment | Medical Status |
|--------|-----------------------|------------------------------------|-------------------|----------------|
| PI | | | | |
| PD | Cause:4038 | Could Not Duplicate Concern | | |
| S | Fires on safe release | Concern:1007 Fired on Safe Release | | Unknown |
| C | | | | |

2/1/07-correspondence from repair-Cust states gun will fire when safety is disengaged.lw

Firearm Information

| Mfg. | Type | Model/Ga. | SKU | Serial | Bbl. | DOM |
|-----------|-------|-----------|-------|---------|------|--------------------------|
| REMINGTON | CF/BA | 7/243 WIN | 26417 | 7821772 | CA | 4/18/2006 11:02:26 PM |

| Date Purchased | Where Purchased | Accessories | Original Owner |
|----------------|---------------------|--------------------------------------|----------------|
| | BILL HICKS & CO LTD | SCOPE,RINGS,TWO PIECE BASE,HARD CASE | U |

CONCERN:FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

REMINGTON/7/CF/BA

| Settlement | Release of Claims | Release Date | Reimbursement | Cash Settlement | Reim. Date APV | Cash Date APV |
|-------------------|-------------------|--------------|---------------|-----------------|----------------|---------------|
| Replace TA at n/c | | | | | | |

| Repair/Replacement Cost | Repair/Replacement Date |
|-------------------------|-------------------------|
| \$25.00 | 2/1/2007 |

2/1/07-Replace TA, check over, clean to restore confidence in rifle.lw

Examination[REMINGTON/CF/BA]

| Part | Sub-Part | Code | Comment |
|-------------|--------------|------|-----------|
| Examination | Examiner | | B.TRAVIS |
| | Exam Date | | 1/31/2007 |
| | Product Type | | RF |
| | Action Type | | A |

| | | | |
|--------------------------|------------------------|-----------------------------|--------------------------------------|
| | Assigned To | | F.SUPRY |
| Cause | 4038 | Could Not Duplicate Concern | |
| Barrel | Description | | 20" 243 WIN |
| | Date Code | | CA |
| | Bore Plugged | False | |
| | Bulged | False | |
| | Fired | False | |
| | Fired while Obstructed | | |
| | Muzzle/Crown Condition | Worn; Functioning | |
| Bolt | Firing Pin | Slightly Worn; Functioning | |
| | Shroud | Slightly Worn; Functioning | |
| | Face | Slightly Worn; Functioning | |
| | Handle | Like new; Functioning | |
| | Stop | Like new; Functioning | |
| Extractor | Condition | Slightly Worn; Functioning | |
| | Cut Condition | Slightly Worn; Functioning | |
| | Ext/Eject Test | False | |
| Locking | Block Condition | ---Select--- | |
| | Lug Condition | Like new; Functioning | |
| | Notch Condition | ---Select--- | |
| Overall | Exterior Condition | Slightly Worn; Functioning | |
| | Stock Condition | Like new; Functioning | |
| | Fore End Condition | ---Select--- | |
| Receiver | Condition | Slightly Worn; Functioning | |
| | Bulged | False | |
| Safety | Description | | STANDARD M/7 SAFETY |
| | Function | Like new; Functioning | |
| Sear | Lift | ---Select--- | .010 |
| | Notch | Like new; Functioning | |
| Tests | Test Fired | False | |
| | Feeding Test | False | |
| Trigger | Condition | Like new; Functioning | |
| | Pull | ---Select--- | 6# |
| | Altered | False | |
| Non-Remington Components | Description | | SCOPE,RINGS,TWO PIECE BASE,HARD CASE |

Repair Inquiry

Repair Number: **RE00124546**

Verify Repair

Serial: 7821772 Model 7 Center Fire Caliber: 243
WIN. Produced: 04/18/2006

Repairman: Charles Swanson

Status: Repairing 2/1/2007 7:58:44 AM

Address Information

Customer:

☒ Received From

Return To:

☐ Received From

Name: BASS PRO SHOPS

BASS PRO SHOPS

Address 1: 3501 PAXTON STREET

3501 PAXTON STREET

Address 2:

PO Box:

PO Box:

City: HARRISBURG

HARRISBURG

State: PA

Zip Code: 17111

Country: US

State: PA

Zip Code: 17111

Country: US

FFL:

Contact / Condition

Problems

Estimate

History / Status

Shipping / Billing

Problems Reported

| Code | Desc |
|------|-----------------------|
| M123 | FORWARD TO PRODUCT SE |

Problems Found

| Code | Desc |
|------|------------------------|
| M106 | COULD NOT DUPLICATE CU |

Repair Notes

Could not duplicate concern. Replacing trigger assb. and checking over and testing to restore confidence in rifle.

Repairman's Comments

CSR Comments

Repair Search

Refresh

Close

PS 8169

Remington

Factory Repair Form

Return to Previous Page

NOTE: Please complete and print this form, and then include it with your firearm.

| | | | |
|--|--|-------------------------------|-------------------|
| Model Number: 7 CDL | | Serial Number: 7821772 | |
| Are you the original owner?: <input type="checkbox"/> YES <input type="checkbox"/> NO | | | |
| Name: BASS PRO SHOPS | | Date of Purchase: _____ | |
| Address (no PO Boxes): 3501 PAXTON STREET | | | |
| City: HARRISBURG | | State: PA | Zip: 17111 |
| Phone (Daytime): 717-565-5261 | | Fax: _____ | |
| E-mail Address: (if e-mail address is provided, notification of receipt and shipment will be sent) _____ | | | |
| E-mail Address: <input type="checkbox"/> I would like to receive future e-mail updates from Remington. | | | |
| Please describe your problem and date of occurrence: | | | |
| <p>CUSTOMER IS SAYING GUN WILL FIRE WHEN SAFETY IS DISENGAGED WITH 1 ROUND IN CHAMBER AND A FULL MAGAZINE.</p> <p><i>could not duplicate concern replace TPA, check over/clean to restore confidence in rifle warranty</i></p> | | | |
| 500 characters left | | | |
| Ammunition Information: | | | |
| Manufacturer: _____ | | Type: _____ | |
| Other (i.e. bullet weight/type, shot size, powder): _____ | | | |
| Handload Information: | | | |
| Powder Used: _____ | | Powder Weight: _____ | |
| Primer Used: _____ | | Reloader Used: _____ | |
| Number of rounds) _____ | | PS 8170 | |

Serial Number: **7821772**Model: **7****RE00124546**

| | |
|--|--|
| How often do you clean the action? (Months or Number of rounds) | |
| How often do you clean the trigger assembly? (Months or Number of rounds) | |
| Brand of lubricant used: | |
| How often do you lubricate the bore? (Months or Number of rounds) | |
| How often do you lubricate the action? (Months or Number of rounds) | |
| How often do you lubricate the trigger assembly? (Months or Number of rounds) | |
| Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual? <input type="checkbox"/> YES <input type="checkbox"/> NO | |
| When was the last time that your firearm was serviced by a Remington authorized repairman/gunsmith?) | |
| What were the services performed?) | |
| NOTE: In order to better service our customers some firearms/parts are sent to a certified Remington Premier Authorized Repair Center. | |
| Ship your INSURED firearm by either UPS or Parcel Post to: Remington Arms Co., Inc. Attn: Arms Service Division 14 Hoefler Avenue Ilion, NY 13357 | |
| ⚠ WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM. :: Record the serial number of your firearm before sending it. :: Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.) :: Remove all accessories from your firearm to prevent loss or damage. :: Provide a return address on both the outside and inside the box. Shipments without a proper return address will be refused. :: Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for damage or loss during shipment, so you may elect to purchase insurance from your carrier. Charge repairs will be processed using the following guidelines: :: Repairs \$75.00 and under will be completed and returned to you C.O.D. (To avoid C.O.D. Charges, please include your credit card number and expiration date with your gun) :: For Repairs over \$75.00, you will receive a written estimate detailing the nature of the repair, applicable taxes and shipping. You will have 30 days to approve the repair estimate. Repairs can be paid by check, money order, or credit card (American Express, Discover, MasterCard, or VISA). If you wish, you can expedite repairs over \$75.00 by setting a pre-authorized amount that can be billed to your credit card. | |

©2005 Remington Arms Company

**Outdoor World****TIM WALLACE**
Gunsmith3501 Paxton Street
Harrisburg, PA 17111
717-565-5261
Fax: 717-564-1949
TWWallace@basspro.com**Remington**

PS 8171

Remington Arms Co., Inc.
Product Service
Legal Case #:701

Case Information

| RE# | Date Opened | Date Opened(PS) | Date Closed | Incident Date | Pre Lit | Lit | Obsolete |
|-----|-------------|-----------------|-------------|---------------|---------|-----|----------|
| | | 11/27/2006 | | 11/18/2006 | | | |

Customer Information

| Type | First Name | Last Name | Street | City | State | Zip | Age | Contact |
|----------|------------|-----------|-----------------|-------|-------|-------|-----|---|
| Reporter | Jim | Brown | 718 Flaglake Rd | Sarah | MS | 38665 | | H 662-560-5223 C 662-403-8199 E jebrown@northwestms.edu |

Incident Information

| Claims | Codes | Repair Est. | Medical Treatment | Medical Status |
|--------------------|---|-------------|-------------------|----------------|
| PI PD S C | Cause:4079 Other - Unexamined Concern:1008 Fired on Bolt Closing | | Unknown | |

11/27/06-Cust claims first round there was a delayed firing. Upon closing the bolt on the next round, the gun fired. He took it to a gunsmith who stated that there was a problem with the trigger assembly. The gunsmith thought it was the sear or spring but did not break down the trigger assembly. He did not want to send the gun in and not be without it for several weeks. He also notated that he did purchase another firearm to hunt with in the meantime.lw

Firearm Information

| Mfg. | Type | Model/Ga. | SKU | Serial | Bbl. | DOM |
|-----------|-------|---------------|-------|----------|------|--------------------------|
| Remington | CF/BA | 7/300 SAUM | 29553 | S7652646 | | 10/10/2002 9:29:38 AM |

| Date Purchased | Where Purchased | Accessories | Original Owner |
|----------------|------------------------------|-------------|----------------|
| | SIMMONS GUN SPECIALTIES I | | U |

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/7/CF/BA

| Settlement | Release of Claims | Release Date | Reimbursement | Cash Settlement | Reim. Date APV | Cash Date APV |
|----------------------|-------------------|--------------|---------------|-----------------|----------------|---------------|
| Replace TA at n/c | | | | | | |

(PS 8172)

| Repair/Replacement Cost | Repair/Replacement Date |
|----------------------------|----------------------------|
|----------------------------|----------------------------|

\$25.00

11/30/2006

11/27/06-emailed ARS to have gun sent to Paducah. Spoke with Charlie at Paducah and asked that he expedite the firearm.lw 11/30/06-Charlie at Paducah inspected the firearm and noted that all 3 trigger screws had been adjusted. Also there was a heavy, sticky oil in the trigger assembly. Cust claims that he has never even taken the stock off of the gun. Possibly his gunsmith may have done something. I advised Charlie to replace trigger assembly at no charge as gesture of goodwill to get the gun back in a safe condition.lw 12/5/06-Received call from Jim Brown. He got the rifle back from Paducah and wanted to notate that the bolt clicks when you open it. He also notated that the safety rubs the side of the bolt when pushing it to fire. He said it does not hinder the function of the safety. He said he would like to use it this season. I offered to get it back to the factory after season if he still is not satisfied.lw

Examination[Remington/CF/BA]

| Part | Sub-Part | Code | Comment |
|------|----------|------|---------|
|------|----------|------|---------|

(PS 8173)

Arms Services - Remington Authorized Repair Centers (RARC)

File Add Repair Review Repair Inquiry Repair Tools Reports Table Maintenance Help

RARC Repair Inquiry

Repair Number: **RP00072630**

Verify Repair

Current Repair Status: **New 11/30/2006 12:59:42 PM**

Repair Center:

Paducah Shooter Supply

3919 Cario Rd.

Paducah, KY 42001 US

Customer:

Jim Brown

718 Flag Lake Rd

Sarah, MS 38665 USA

Phone: (662) 562-4091

Email:

Repair Information

Repair Charge Breakdown

Repair History

Accounting

Reference Nbr:

Repair Type: **Firearm**

Model ID: **7**

Serial Nbr: **S7652646**

Gauge/Caliber: **300 SAUM**

Barrel Date:

Date Received: **11/29/2006**

Date Returned: **11/30/2006**

Date to Factory:

Date Produced

Repair Codes:

M178

Parts:

F97954 - 7 SS TRIGGER ASSB

Repair Text:

Check firing pin and ISS System. Factory seal has been removed from all screws and all have been reset. Very heavy oil/lube inside trigger assy making it hang up. replace trigger assy for safety reasons per

Repair Search

Refresh

Close

PS 8174

Remington Arms Co., Inc.
Product Service
Legal Case #:823

Case Information

| RE# | Date Opened | Date Opened(PS) | Date Closed | Incident Date | Pre Lit | Lit | Obsolete |
|--------|-------------|-----------------|-------------|---------------|---------|-----|----------|
| 121425 | 12/14/2006 | 12/14/2006 | 12/14/2006 | | | | |

Customer Information

| Type | First Name | Last Name | Street | City | State | Zip | Age | Contact |
|----------|-------------------|-------------------|-----------------------------|---------|-------|-------|-----|--------------------|
| Reporter | Lewis Matteson | Lew's Gun Shop | 44 Dexter Road/PO Box 36 | Corinna | ME | 04928 | | W 207-278- 4773 |

Incident Information

| Claims | Codes | Repair Est. | Medical Treatment | Medical Status |
|--------|-----------------------|-----------------------|-------------------|----------------|
| PI | | | | |
| PD | Cause:4015 | Improper Maintenance | | |
| S | | | Unknown | |
| C | Fires on safe release | Concern:1007 | | |
| | | Fired on Safe Release | | |

12/15/06-correspondence from repair-New Model Seven, never sold. Fires on safe release.lw

Firearm Information

| Mfg. | Type | Model/Ga. | SKU | Serial | Bbl. | DOM |
|----------------|----------------------|---------------|----------------|---------|------|-------------------------|
| REMINGTON | CF/BA | 7/7MM SAUM | 29543 | 7783756 | CX | 4/10/2003 8:30:17 AM |
| Date Purchased | Where Purchased | Accessories | Original Owner | | | |
| | HENRYS TACKLE LLC | | Y | | | |

CUST.CONCERN:FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

REMINGTON/7/CF/BA

| Settlement | Release of Claims | Release Date | Reimbursement | Cash Settlement | Reim. Date APV | Cash Date APV |
|------------|-------------------|--------------|---------------|-----------------|----------------|---------------|
| | | | | | | |

Replace TA
at n/c

| Repair/Replacement Cost | Repair/Replacement Date |
|-------------------------|-------------------------|
| 25.00 | 12/15/2006 |

PS 8175

12/15/06-replacing TA, check over, clean at n/c.lw

Examination[REMINGTON/CF/BA]

| Part | Sub-Part | Code | Comment |
|-------------|------------------------|-----------------------|--|
| Examination | Examiner | | B.TRAVIS |
| | Exam Date | | 12/14/2006 |
| | Product Type | | RF |
| | Action Type | | A |
| | Assigned To | | F.SUPRY |
| Cause | 4015 | Improper Maintenance | TRIG AND TRIG PIN RUSTED, TRIG BINDING |
| Barrel | Description | | 22" 7MM SAUM |
| | Date Code | | CX |
| | Bore Plugged | False | |
| | Bulged | False | |
| | Fired | False | |
| | Fired while Obstructed | | |
| | Muzzle/Crown Condition | Like new; Functioning | |
| Bolt | Firing Pin | Like new; Functioning | |
| | Shroud | Like new; Functioning | |
| | Face | Like new; Functioning | |
| | Handle | Like new; Functioning | |
| | Stop | Like new; Functioning | |
| Extractor | Condition | Like new; Functioning | |
| | Cut Condition | Like new; Functioning | |
| | Ext/Eject Test | False | |
| Locking | Block Condition | ---Select--- | |
| | Lug Condition | Like new; Functioning | |
| | Notch Condition | ---Select--- | |
| Overall | Exterior Condition | Like new; Functioning | |
| | Stock Condition | Like new; Functioning | |
| | Fore End Condition | ---Select--- | |
| Receiver | Condition | Like new; Functioning | |
| | Bulged | False | |
| Safety | Description | | STANDARD M/7 SAFETY |
| | Function | Like new; Functioning | |

| | | | |
|---------|--------------|---------------------------|----------------------------------|
| Sear | Lift | ---Select--- | .011 |
| | Notch | Like new; Functioning | |
| Tests | Test Fired | False | |
| | Feeding Test | False | |
| Trigger | Condition | Like new; Not Functioning | TRIG AND PIN RUSTED TRIG BINDING |
| | Pull | ---Select--- | 10+# |
| | Altered | False | |

(PS 8177)

Corporate BATF

| Modelid | Material | ProdLoc | ProdDate | Description |
|---------|----------|---------|-----------|---|
| SEVEN | 29543 | ILN | 4/10/2003 | MODEL SEVEN.TM LAMINATED STOCK BOLT ACTION CENTERFIRE RIFLE 22" BBL 7mm REM SA ULTRA MAG |

| Date | Code | Loc | Customer Name | Zip Code | Delivery | UserID | Activity Reason |
|------------|------|-----|-------------------|----------|------------|--------|-----------------|
| 2003/05/13 | SHIP | OHL | HENRYS TACKLE LLC | 28570 | 0080942332 | almolt | |

FFL:1-56-031-01-6A-40595

Location: Arms Services

Not on File at this location

Location: Custom Gun Shop

Not on File at this location

Location: Ilion Plant

| Modelid | Material | ProdLoc | ProdDate | Description |
|---------|----------|---------|------------|---|
| SEVEN | 29543 | ILN | 04/10/2003 | MODEL SEVEN.TM LAMINATED STOCK BOLT ACTION CENTERFIRE RIFLE 22" BBL 7mm REM SA ULTRA MAG |

| Status | Date | Inv Loc | OverPack | Pallet | Transfer | Shipment | DelNoteNbr | HoldStatus |
|-------------|------------|---------|----------|----------|----------|----------|------------|------------|
| Transferred | 04/11/2003 | Staging | | P2023212 | T2001584 | | | |

| History: | Date | Action | User | Activity Description |
|----------|------------|-------------|-----------|----------------------------------|
| | 2002/09/12 | Assigned | lewisrj | SEVEN |
| | 2003/01/16 | Rolled | raymj | |
| | 2003/04/10 | Packed | rankinsif | .ABN9543-1.FA7275.FB15168.FC8181 |
| | 2003/04/10 | Print | rankinsif | Packer Print |
| | 2003/04/10 | Warehoused | murrayfb | N9543-1 |
| | 2003/04/11 | Transferred | macrinakl | To: OHL on T2001584 |

Location: Mayfield

Not on File at this location

Location: Memphis

| Modelid | Material | ProdLoc | ProdDate | Description |
|---------|----------|---------|------------|---|
| SEVEN | 29543 | ILN | 04/10/2003 | MODEL SEVEN.TM LAMINATED STOCK BOLT ACTION CENTERFIRE RIFLE 22" BBL 7mm REM SA ULTRA MAG |

| Status | Date | Inv Loc | OverPack | Pallet | Transfer | Shipment | DelNoteNbr | HoldStatus |
|---------|------------|-----------|-----------|--------|----------|----------|------------|------------|
| Shipped | 05/13/2003 | Intransit | 010310499 | | T2001584 | 110179 | 0080942332 | |

| History: | Date | Action | User | Activity Description |
|----------|------------|--------------|---------|---|
| | 2003/04/14 | Received | almolt | From: ILN on T2001584 |
| | 2003/04/15 | LocChange | REK | Location: RIFLE RF |
| | 2003/04/22 | LocChange | TEH | Location: FA46A54 RF |
| | 2003/05/01 | LocChange | PAI | Location: FA46A54 RF |
| | 2003/05/12 | OverPack Add | wrightc | into OP: 010310499 DMS Staging |
| | 2003/05/12 | ShipUnitAdd | SKW | Shmt:110179 PO:C030225-02 SU:S10356670 - RF |
| | 2003/05/13 | Shipped | almolt | Shmt: 110178 Delv: 0080942332 |

Local BATF

| Date | Code | Loc | Customer Name | Zip Code | Delivery | UserID | Activity Reason |
|------------|------|-----|-------------------|----------|------------|--------|-----------------|
| 2003/05/13 | SHIP | OHL | HENRYS TACKLE LLC | 28570 | 0080942332 | almolt | |

Location: Arms Service Repairs

| Repair Nbr | StatusDate | SerialNbr | Replacement | Description |
|------------|------------|-----------|-------------|--|
| RE00121425 | 12/14/2006 | 7783756 | | Model 7 Center Fire Caliber: 7 MM REM SA ULTRA MAG |

Location: Remington Authorized Repair Centers

Not on File at this location

Location: Non-SAP Serial Number Tracking

Not on File at this location

(PS 8178)

LEW'S GUN SHOP

CASE #
823

44 Dexter Road
P O Box 36
Corinna, ME 04928

12/4/03

FFL#6-01-019-01-5L-05713
Tel: 207-278-4773
Fax 207-278-4774

10th

December 05, 2006

011
22"

Remington Arms Company, Inc.
Arms Service Division
14 Hoefler Avenue
Ilion, NY 13357

I am returning herewith a new Model Seven LS, Ser#7783756. I obtained this gun new on September 10, 2003, but it has never sold. In checking it over a few days ago, I found a problem which must be corrected before I can resell it.

Releasing the safety after the gun is cocked will cause it to fire. Please do whatever is needed to take care of the defect and return as promptly as possible. Please return it in the original box!

Thank you.

Lewis Matteson
Lewis Matteson
LEW'S GUN SHOP

171475

Serial
Number:

7783756

Model: **7**



RE00121425

TRIG. + TRIG. Pin checked.
TRIG. Binding:
Replace TPA, check over,
clean AT N/C
#230145

RECEIVED
DEC 15 2006

BY:.....

(PS 8179)

Arms Services Repair & Estimate System

File Add Repair Estimate Repair Expedite Repair Inquiry Repair Tools CSR Tools Reports Table Maintenance System Maintenance Help

Repair Inquiry

Repair Number: **RE00121425** Serial: 7783756 Model 7: Center Fire Caliber 7
 Verify Repair **High Priority** MM REM SA ULTRA MAG Produced: 04/10/2003 Repairman:
 Status: New 12/14/2006 7:36:25 AM

Address Information

| | | | |
|--|--|--|--|
| Customer: <input checked="" type="radio"/> Received From | | Return To: <input type="radio"/> Received From | |
| Name: LEWS GUN SHOP | | LEWS GUN SHOP | |
| Address 1: 44 DEXTER ROAD | | 44 DEXTER ROAD | |
| Address 2: PO Box: | | PO Box: | |
| City: CORINNA | | CORINNA | |
| State: ME Zip Code: 04928 Country: US | | State: ME Zip Code: 04928 Country: US | |
| FFL: <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> | | | |

Contact / Condition

Problems

Estimate

History / Status

Shipping / Billing

Contact Information

Phone: 207 278 4773
 Fax: 207 278 4774
 Email:
 Comments:

Received Condition

Fair
 Condition Notes:
 CSR Notes:

Accessories Received

| Code | Desc | Qty |
|------|-----------|-----|
| A007 | With Stud | 2 |
| A030 | ISS Key | 2 |

Repair Search

Refresh

Close

PS 8180

Imwatson 12/18/2006 5:21 PM CAPS NUM INS SCRL

Start 2 Micr... 4 Inte... Arms S... Search f... P-touch... Microsof... Serial N... 4 SAP... FullShot... 97% 5:21 PM