

A&C GUNSMITHING SHOP

15 So. 300 West
Veyo, Utah 84782
435-632-3006

To Remington Repair Center,
In Ref. to Model 700 SN# S6298697

March 20, 2000

This rifle is approximately two years old. The buyer used it for the first time on an elk hunt in 1998 here in Utah and found the trigger to be very unpredictable, in that it would be light one time and heavy the next. Before the elk hunt last year he brought it in to my shop and I tested it with my trigger pull gage. The first two or three times it was about five pounds. Then it went to nine pounds. The next time it was two and a half pounds. I tested it probably fifteen times and was not able to get a consistant pull.

The gun was brought in only three days before he needed it last year so I didn't have the time to send it back to you at that time, so he asked if there was a way that I could just lighten the trigger pull and he would just take it and bring it back to have it done right. Well he had it discharge a couple of times when he released the safety, so it was still set aside and brought back in to us last week.

We would apprreciate having this fine weapon repaired and returned, at least he did give us the time to have it done the right way this time. Thank you for your high quality firearms and service. They are both what your industry is all about.

3/29/00

*Trigger unpredictable
& has been lightened*

Go ahead

Sincerely

Arthur C. Durfee
Arthur C. Durfee (owner)

1007
4006

*Trig adj & stop screws altered
w/ton duty*

Replace trigger assembly complete at 50% cost

Serial Number: **S6298697**

Model: **700**



RE00007062