

Repair Order Number



Repair Order Number RE00092217	Description/Serial Number 6540941	Repairman - Chuck Dekanek Date Received - 2/9/2005
Account # - R-	Model 700 Center Fire Caliber: 243 WIN	Estimate Date - 2/8/2005 Current Date - 2/11/2005
Customer AB NGTON TOWNSHIP POLICE DEPARTMENT 1166 OLD YORK ROAD SGT BRUC MOUAT AB NGTON. PA 19001 US		Return To AB NGTON TOWNSHIP POLICE DEPA 1166 OLD YORK ROAD SGT BRUC MOUAT AB NGTON. PA 19001 US
Phone (H) (215)-576-6503 Phone (W) (215)-536-1100		Fax (215)-886-1455 Email

Reported		Problems		Found	
M123	FORWARD TO PRODUCT SERVICE FOR INSPECTION	M123	FORWARD TO PRODUCT SERVICE F		
M240	BOLT LOCK SAFETY MODIFICATION				
M992	RIFLE DISCHARGED AFTER PUSHING SAFETY OFF				

Material #		MaterialDesc	Quantity Needed	Quantity From Inv	Quantity From Kit	Warranty (Y/N)
Part						
F26345		700 TRIG ASSB RH	1	1	0	Y
Part Total:			1	1	0	
Service						
4000104		ARMS SERV SHIPPING & HANDLING	0	0	0	Y
4000116		GR-LABOR	20	20	0	N
4000119		GR-TEST	1	1	0	Y
4000294		GR-CHECK TPA	1	1	0	Y
Service Total:			22	22	0	

Condition	STOCK MARRED				
ProblemNotes	Could not duplicate concern. Trigger set screws altered and trigger works sluggish/sticky from dried lubrication residue. Replace trigger assembly, clean and check over for cost of safety modification program of \$20.00.				
Repairman	Proof	Clean	Test	Target	Pattern
Gallery Tester	Date	Date	Date	Date	Date