Remington.

TRACKING DOCUMENT

Repair Order Number



Repair Order Number

RE00077874

G6300928

Repairman -Bruce Travis

Account # - R-

Model 700 Center Fire Caliber: 300 REM

Description/Serial Number

Date Received · 2/27/2004

Estimate Date -

ULTRA MAG

Current Date - 3/4/2004

Customer

ACE HARDWARE 2200 LAKESIDE DRIVE Return To

ACE HARDWARE 2200 LAKESIDE DRIVE

LYNCHBURG. VA 24501 US

LYNCHBURG. VA 24501 US

Phone (H)

(804)-525-2556

Fax

Phone (W) (804)-664-7464

Email Open Hame

Reported	2 14 14 15 15 15 15 15 15 15 15 15 15 15 15 15	items .	Found
M123	FORWARD TO PRODUCT SERVICE	M123	FORWARD TO PRODUCT SERVICE FO
	FOR INSPECTION		
M993	FIRED WITH SAFE ON	[t .	
1	·	1	
		t	

Material #	<u>MaterialDesc</u>		Quantity	Quantity	<u>Quantity</u>	<u>Warranty</u>
			<u>Needed</u>	From Inv	From Kit	(Y/N)
Part		. *				
F26345	700 TRIG ASSB RH	4	1	1	0	Y
Part	Total:	Á	1	1		
Service		i				
4000104	ARMS SERV SHIPPING & HANDLING	Ŀ	0	0	0	Y
4000119	GR-TEST	<u>}</u>	1	1	0	Y
Service	Total:		1	1	0	

ProblemNotes	upon receipt trigger would not retract from rusty trigger pin and rust between connector and trigger - rusty from unknown source. replace trigger assm at no charge.						
			•				
Repairman	Proof	Clean	Test	Target	Pattern		
Gallery Tester	Date	Date	Date	Date	Date		