

from: Alevedo Lee
— 6250 Walden Rd.
Beaumont, TX 77707

To: Remington Arms Company
14 Hoefler Ave.
Ilion, New York
13357

Serial
Number:

6527851

Model: 700



RE00031616

AW = 3/72

Remington Arms Company
14 Hoefler Ave.
Ilion, New York 13357

Dear Gunsmith,

This Remington 30/06 Model #700 has been in our family for many years. It is an excellent shooting rifle. However, on three separate occasions it has FIRED while moving the SAFETY LEVER from SAFETY to the FIRING position, each time my finger was nowhere near the trigger. The last time this happened it narrowly missed shooting my SON in the back. Therefore I had no choice, but to stop using this rifle. This rifle is to be handed down to a grandson, so I do not wish to have the rifle replaced. I feel there is a defective part in the firing mechanism. This gun has never been worked on or modified in anyway. I would appreciate your help in rectifying any problems this rifle has, and helping me preserve this family heirloom. Thank you in advance for your help.

Respectfully,

Lee Acevedo Jr.
6250 Walden Road
Beaumont, Texas 77707
Wk phone: 409-842-4437
Hm phone: 409-898-4967

RT#
31616

Could not duplicate.

Altered adjustments, dirty TA, Bolt Release and
Safety sear cam sticky.

Instal new TA at $\frac{1}{2}$ normal charges
as gesture of goodwill.

FLS 9/4/01