

#### COMMENTS

ORDER  
R 94-34285

|         |                    |
|---------|--------------------|
| INITIAL | CUSTOMER ORDER NO. |
|---------|--------------------|

W/PACHMAYR RECOIL PAD

|               |             |           |               |                   |                 |
|---------------|-------------|-----------|---------------|-------------------|-----------------|
| FPS           |             |           |               |                   |                 |
| DATE RECEIVED | DATE OPENED | DATE CODE | SERIAL NUMBER | NEW SERIAL NUMBER | MODEL AND GRADE |
| 11/28/94      | 11/30/94    | RV 11-79  | R6056991      |                   | 788 243 WIN     |
| ACCESSORIES   |             | W/STUDS   | L/CLIP        | L/REAR SIGHT      |                 |

FROM:

SHIP TO:

ADELUNG, DENNY  
2518 ENCINO LN.  
SUGAR LAND

TX 77477

ADELUNG, DENNY  
2518 ENCINO LN.  
SUGAR LAND

TX  
77477

CUST NO: 109231 C.O.D.

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

PROM. DATE

ESTIMATED

VIA

**WRITE**

UFS

**GUN CONDITION**

☐ NEW  
☒ LIGHTLY WORN  
☐ WORN  
☐ VERY WORN  
☐ UNREPAIRABLE  
☐ MARRED

☒ REPAIR CHARGE

**EXCISE**

TAX

INSURANCE

UPS

PARCEL POST

|       |  |
|-------|--|
| TOTAL |  |
|-------|--|

28

| CUSTOMER CONCERN | AMMO | FUNCTION | FINISH | ACCURACY | FIT | INSPECT |
|------------------|------|----------|--------|----------|-----|---------|
|------------------|------|----------|--------|----------|-----|---------|

|               |    |                             |    |    |    |  |
|---------------|----|-----------------------------|----|----|----|--|
| CYCLE         | A1 | gun fired on safety release |    |    |    |  |
| TRIGGER GROUP |    | B2                          |    | E1 | F1 |  |
| BOLT ASSY.    |    | B3                          |    | E2 | F2 |  |
| BARREL ASSY.  |    | B4                          | D1 | E3 | F3 |  |
| REC. ASSY.    |    | B5                          | D2 | E4 | F4 |  |
| WOOD          |    |                             | C1 | D3 | E5 |  |
| METAL         |    |                             | C2 |    |    |  |

MAIN FAULT mfg. 11/79 Trigger would not return after being pulled due to jammy residue in trigger assy. Exchange trigger at a spec. price, as a gesture of good will and to restore customers confidence in rifle.

## PARTS

**COMMENTS**

Frigger Assy.

Some rest on receiver

See owner's manual for cleaning  
and maintenance

|                         |       |                   |                  |        |         |
|-------------------------|-------|-------------------|------------------|--------|---------|
| REPAIRMAN<br><i>FB.</i> | PROOF | CLEAN<br><i>✓</i> | TEST<br><i>✓</i> | TARGET | PATTERN |
| GALLERY TESTER          | DATE  | DATE              | DATE             | DATE   | DATE    |

OFFICE COPY

BD6925 REV. 1

PS00308