

the desk of

Denny Adelung
2518 Encino Ln.
Sugar Land, TX
77477

11/21/94

(713) 242-6037

Remington Model 788
S/N B6056991

Whom It May Concern,

Pls. repair the trigger & safety mechanism
of this rifle. The Problem is as follows;

- Loaded (1) round into chamber
- Moved safety to "F" position
- Pulled trigger, gun would not discharge
- Ret'd safety to "S" position & re-cycled bolt.
- attempted to discharge rifle.
- Rifle did not discharge
- Moved safety to "F" position & pushed forward. Gun discharged !! Not good!
- Pls. repair - call w/ estimate if unusually costly.

Thanks,
D. Adelung

call w/ estim
stly.

The
D.