

RECEIVING AND ESTIMATING REPORT

COMMENTS

to Product Service

ORDER
R 94-17323

INITIAL

CUSTOMER ORDER NO.

FPS

DATE RECEIVED
06/01/94

DATE OPENED
06/02/94

DATE CODE
AP 3-67

SERIAL NUMBER
263123

NEW SERIAL NUMBER

MODEL AND GRADE

700 308 WIN ADL

ACCESSORIES

W/STUDS

FROM:

ADVANCED ARMORMENT DESIGN
113 E MAIN ST
ROUND ROCK TX 78664

SHIP TO:

ADVANCED ARMORMENT DESIGN
113 E MAIN ST
ROUND ROCK TX 78664

CUST NO: 024353 C.G.D.L.

ACCOUNT NUMBER

ACCOUNT NUMBER INC

WRITE ☐

FROM DATE

ESTIMATED

VIA

6-27

UPS

GUN CONDITION

☐ NEW

☐ LIGHTLY WORN

☒ WORN

☐ VERY WORN

☐ UNREPAIRABLE

☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

20.00

8.00

28.00

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

B1

TRIGGER GROUP

B2

BOLT ASSY.

B3

BARREL ASSY.

B4

REC. ASSY.

B5

WOOD

C1

METAL

C2

MAIN FAULT

Upon receipt, we could not duplicate the customer concern. Examination did reveal that the trigger adjustment had been moved from its set outside the factory. The sear has been moved and the trigger set moved.

PARTS

1 3/4 lbs, new left - .009

COMMENTS

Trigger and trigger assembly are covered with heavy black substance. Good cleaning would.

26345

Recheck complete trigger assembly and clean action at 1/2 normal repair cost as per quote of your work.

REPAIRMAN

PROOF

CHECK

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 1/84

*to A/S
6/28/94*