

CREDIT CARD

CUSTOMER CONCERN	FUNCTION	PROOF	ACCURACY
CYCLE	2nd time		
TRIGGER ASSM			
CHARGE			
BARREL			
RECESS			
WOOD			
METAL			
WART FAULT			

Went to replace trigger. However, the trigger mechanism was made to trigger manually without use of trigger. Trigger part replaced.

26345 Trigger assm. Charge & Credit Card. M/C 5413 4402 1600 7755. Exp. 3/94. Go ahead.

REPAIRMAN R.B.	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD9999 REV. 1/92