

<b>File Number:</b>	16138		<b>Arms Service number:</b>	26404	
<b>Last Name:</b>	AHLMAN'S		<b>First Name:</b>		
<b>Street:</b>	9525 WEST 230TH STREET		<b>City:</b>	MORRISTOWN	
<b>State:</b>	MN	<b>Zip:</b>	55052	<b>Home Ph:</b>	
<b>Work Ph:</b>	507-685-4244	<b>Product Type:</b>	F	F A T O	
<b>Type Concern:</b>	S	PI PD P S	<b>Concern Code:</b>	1007	
<b>Concern:</b>	FIRED ON SAFE RELEASE				
<b>Cause Code:</b>	4040	<b>Cause:</b>	OTHER - UNSPECIFIED OR UNDETERMINED		
<b>Assigned To:</b>	SUPRY	<b>Classification:</b>	UND	UNJ UNC UND	
<b>Settlement Detail:</b>	INSTALL NEW TA N/C		<b>Settlement Amount:</b>	\$65.00	
<b>Date Opened Rem:</b>	4/23/01	<b>Date Opened by P/S:</b>	4/23/01	<b>Caliber:</b>	270
<b>Date of Incident:</b>		<b>Date Closed:</b>	4/23/01	<b>Bullet Weight:</b>	
<b>Date to Analysis:</b>		<b>Date from Analysis:</b>		<b>Manufacturer:</b>	
<b>Model:</b>	700	<b>Serial:</b>	B6585313	<b>Date Code:</b>	KE
<b>RAMAC:</b>	700	<b>Date Mfgd:</b>	5/1/84		
<b>Litigation:</b>	<input type="checkbox"/>	<b>PreLitigation:</b>	<input type="checkbox"/>	<b>Obsolete:</b>	<input type="checkbox"/>
<b>Custody:</b>		<b>Comments:</b>	Could not duplicate customer concern - As received the trigger pull was sluggish, and the safety button was difficult to move - Install new TA at n/c as gesture of goodwill.		
<b>Time of Modification:</b>	8:28:27 AM				
<b>Date of Modification:</b>	4/23/01				