

E = 5/84

could not duplicate

is received trigger pull
sluggish, safe works hard

install new TA w/c

charge 230145

FLS 4/23/01

Serial Number: **B6585313**

Model: **700**



RE00026404

AHLMAN'S

9525 West 230th Street
MORRISTOWN, MN 55052

REMINGTON ARMS
111 HOFFER AVE.
ILION, N.Y. 13357

TO:

Remington Arms Co

62662

This firearm has the following defect:

Safety works hard
and it fired when he pushed Bolt Release
he Request warranty (Safety Reason) Push

Please repair under warranty at no charge and return directly to us. If not covered by warranty, please send repair estimate before proceeding.
Thank you.

26404

Ahlman's
9525 • 230TH STREET WEST
MORRISTOWN, MN 55052-5020
(507) 685-4244