

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 91-22334

INITIAL 111	CUSTOMER ORDER NO. 91379					
DATE RECEIVED 0/31/91	DATE OPENED 11/06/91	DATE CODE CI 4-88	SERIAL NUMBER C6244930	NEW SERIAL NUMBER	MODEL AND GRADE 700 280	MTN
ACCESSORIES W/STUDS						

FROM:

AHLMANS
ROUTE 1 BOX 20
MORRISTOWN
USA

MN 55052

SHIP TO:

AHLMANS
ROUTE 1 BOX 20
MORRISTOWN
USAMN
55052

CUST NO: 002719 WILM

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐ CLEAN/TEST	PROM. DATE	ESTIMATED	VIA UPS
UN CONDITION ☐ NEW ☐ LIGHTLY WORN ☐ WORN ☐ VERY WORN ☐ UNREPAIRABLE					REPAIR CHARGE EXCISE TAX INSURANCE UPS PARCEL POST TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
YCLE	A1	B1				
RIGGER GROUP		B2			E1	F1
OLT ASSY.		B3			E2	F2
ARREL ASSY.		B4		D1	E3	F3
EC. ASSY.		B5		D2	E4	F4
OOD			C1	D3	E5	F5
ETAL			C2			

IN FAULT

No fault found - rifle and trigger assembly operate properly in every respect - trigger is made to malfunction - Rifle in as new condition.
Trigger pull measured to be 5 pounds; rear lift .011"

RTS

COMMENTS

Offer to return rifle as-is
or, we can install a new trigger
assembly at a reasonable cost, as a
gesture of good-will, if it will better
restore confidence in the rifle.

REPAIRMAN [Signature]	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 8/91

PS00354

TO: Remington

391379

This firearm has the following defect: Ham trigger

Went off By accident

Please repair under warranty at no charge and return directly to us.
If not covered by warranty, please send repair estimate before

