

RECEIVING AND ESTIMATING REPORT

CUST NO: 002719 WILM		COMMENTS W/BUSHNELL 3X9 SCOPE			
TIAL	CUSTOMER ORDER NO.				
JM					
RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	MODEL AND GRADE	ORDER
9/07/91	10/09/91	LY 2-74	6722430	700 30-06 ADL	R 91-20310
ACCESSORIES	W/STUDS	SCOPE MNTS	SCOPE BASE	HARD CASE	

OM:

AHLMANS
ROUTE 1 BOX 20
MORRISTOWN
USA

MN 55052

SHIP TO:

AHLMANS
ROUTE 1 BOX 20
MORRISTOWN
USA

MN
55052

COUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	PROM. DATE	ESTIMATED 10-18	VIA UPS
--------------	--------------------	--------------------------------	------------	------------	--------------------	------------

AIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
------------	-----	-----------	-----	-------------	-------

IN CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED

STOMER'S REQUEST: *gun fires when unloading*

N FAULT: *Cannot duplicate complaint, cannot make rifle malfunction in any way. Trigger-safety assembly operates normally in every respect. Trigger pull 5 1/4 #; Head lift .007"*

ITS	<i>Offer to return rifle as-is, or, offer to replace trigger assembly at normal cost as a gesture of good-will, if it will better restore confidence in the rifle.</i>					
	REPAIRMAN BWT	PROOF	CLEAN	TEST	TARGET	PATTERN
	GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 7/90

PS00357

RECEIVED

TO: Remington

This firearm has the following defect: gun fires
when unloading

Please repair under warranty at no charge and return directly to us.
If not covered by warranty, please send repair estimate before
proceeding. Thank you.

AHLMAN'S INC. Rt. 1, Box 20, Morristown, MN 55052