

RECEIVING AND ESTIMATING REPORT

WEAVER SCOPE K4 *in scope Cabinet*
W/ SEE THROUGH MNTS

INITIAL LCS	CUSTOMER ORDER NO. 86701	DATE RECEIVED 12/12/90		DATE OPENED 12/17/90	DATE CODE 76	SERIAL NUMBER A6309135	MODEL AND GRADE 700 243 BDL	ORDER R 90-32916
ACCESSORIES W/STUDS								

FROM:

AHLMAN'S
ROUTE 1 BOX 20
MORRISTOWN MN 55052

SHIP TO:

AHLMAN'S
ROUTE 1 BOX 20
MORRISTOWN MN 55052

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE <input type="checkbox"/>	CLEAN/TEST	PRON. DATE	ESTIMATED	VIA UPS
----------------	--------------------	--------------------------------	------------	------------	-----------	-------------------

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
---------------	-----	-----------	-----	-------------	-------

GUN CONDITION:

CUSTOMER'S REQUEST

☐ NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED

"Fires when safe is parked off"

MAIN FAULT

*no fault found - trigger and safety assembly function properly.
Trigger pull 5 pounds; Bear-left .006"*

Cannot duplicate complaint.

PARTS

*Offer to return rifle as-is or, we
can install a new trigger assembly
at a normal cost, as a gesture of
good-will if it will better restore
confidence in the rifle.*

REPAIRMAN <i>[Signature]</i>	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

RD6925 REV. 7/90

PS00375

86701

TO: Rem

This firearm has the following defect: fires when
sate is pushed off

Please repair under warranty at no charge and return directly to us.
If not covered by warranty, please send repair estimate before
proceeding. Thank you.

AHLMAN'S INC. Rt. 1, Box 20, Morristown, MN 55052