

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER

R 94-26268

INITIAL

CUSTOMER ORDER NO.

JJM

DATE RECEIVED
09/13/94DATE OPENED
09/14/94DATE CODE
EY 10-74SERIAL NUMBER
6794592

NEW SERIAL NUMBER

MODEL AND GRADE
700 30-06

BDL

ACCESSORIES

W/STUDS

SCOPE BASE

L/SIGHTS

FROM:

AHLMANS
RTE 1 BOX 20
MORRISTOWN

MN 55052

SHIP TO:

AHLMANS
RTE 1 BOX 20
MORRISTOWN

MN

55052

CUST NO:002719 WILM L

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

PROM. DATE

ESTIMATED

VIA

9-19-94

UPS

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☒ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☒ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

20.00

8.00

28.00

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2				F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT

Upon receipt the rifle was in operation. The firing pin would follow down when closing the bolt. Examination revealed that the trigger assembly components are seized up, from being covered with a heavy sticky greasy substance. This 1974 rifle has been properly maintained.

PARTS

COMMENTS

Replace the complete trigger assembly with Remington at 12.00 and repair cost, as a gesture of good will

Go ahead

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 1/94

PS00387

NEEDLE AND ESTIMATING REPORT

TO: Ren

fires

This firearm has the following defect:

When closing bolt

Please repair under warranty at no charge and return directly to us. If not covered by warranty, please send repair estimate before proceeding. Thank you.

AHLMAN'S INC. Rt. 1, Box 20, Morrisstown, MN 55052