

File Number:	17028		Arms Service number:	36701	
Last Name:	AKERS		First Name:	DONALD	
Street:	21562 140TH AVE		City:	TUSTIN	
State:	MI	Zip:	49688	Home Ph:	231-775-4320
Work Ph:		Product Type:	F	F A T O	
Type Concern:	S	PI PD P S	Concern Code:	1007	
Concern:	FIRED ON SAFE RELEASE				
Cause Code:	4040	Cause:	OTHER - LOOSE TA		
Assigned To:	SUPRY	Classification:	UND	UNJ UNC UND	
Settlement Detail:	REPAIR N/C		Settlement Amount:	\$50.00	
Date Opened Rem:	12/01/2001	Date Opened by P/S:	12/01/2001	Caliber:	243
Date of Incident:		Date Closed:	12/12/2001	Bullet Weight:	
Date to Analysis:		Date from Analysis:		Manufacturer:	
Model:	788	Serial:	A6096295	Date Code:	AI
RAMAC:	788	Date Mfgd:	04/19/1976		
Litigation:	<input type="checkbox"/>	PreLitigation:	<input type="checkbox"/>	Obsolete:	<input checked="" type="checkbox"/>
Custody:		Comments:	As received the front screw holding the TA to the receiver was so loose that the housing would drop too low to allow the sear to hold the firing pin, the TA was extremely dirty, with gummy, sticky residue. Tightened screw - TA functioned properly. Check out completely, clean, test and return to customer n/c.		
Time of Modification:	7:35:26 AM				
Date of Modification:	12/12/2001				