

File Number: 19593		Arms Service number: 73865	
Last Name: AKERS		First Name: LARRY	
Street: 10675 SONTAG RD		City: MARTINSVILLE	
State: VA	Zip: 24112	Home Ph:	
Work Ph:	Product Type: F F A T O		
Type Concern: S	PI PD P S	Concern Code: 1008	
Concern: FIRED ON BOLT CLOSING			
Cause Code: 4040	Cause: OTHER - UNSPECIFIED OR UNDETERMINED		
Assigned To: SANITA	Classification: UNJ	UNJ UNC UND	
Settlement Detail: REPLACE TRIGGER ASSEM AT SPEC PRICE	Settlement Amount: \$0.00		
Date Opened Rem: 12/9/2003	Date Opened by P/S: 12/9/2003	Caliber:	
Date of Incident:	Date Closed: 12/9/2003	Bullet Weight:	
Date to Analysis:	Date from Analysis:	Manufacturer: REM	
Model: 700	Serial: 6523889	Date Code: LW	Date Mfgd: 2/1/1972
RAMAC: 700	Litigation: <input type="checkbox"/>	PreLitigation: <input type="checkbox"/>	Obsolete: <input type="checkbox"/>
Custody:	Comments: Upon receipt the rifle fired on bolt closing from the trigger stop screw being removed from the trigger housing, the trigger adj screw re-set, and the trigger components being covered with sticky substance. Poor maintenance Repair and shipping documents 1/23/04.		
Time of Modification: 10:39:40 AM			
Date of Modification: 12/9/2003			

PS00419