

Repair Order Number



Repair Order Number RE00073865	Description/Serial Number 6523889 REPLACEMENT S6481200	Repairman - Herb Brown
Account # - R-	Model 700 Center Fire Caliber: 25-06	Date Received - 12/11/2003
	VARMIN	Estimate Date - 12/9/2003
		Current Date - 1/15/2004
Customer LARRY AKERS 10675 SONTAG RD MARTINSVILLE, VA 24112 US		Return To LARRY AKERS 10675 SONTAG RD MARTINSVILLE, VA 24112 US
Phone (H) (540)-483-7929		Fax
Phone (W)		Email chelsamsky@sitestar.net

Reported		Problems		Found	
M123	FORWARD TO PRODUCT SERVICE FOR INSPECTION	M123	FORWARD TO PRODUCT SERVICE FOR		
M240	BOLT LOCK SAFETY MODIFICATION				
M992	FIRES WHILE LOADING				

Material #		MaterialDesc		Quantity Needed		Quantity From Inv		Quantity From Kit		Warranty (Y/N)	
Service		4000104 ARMS SERV SHIPPING & HANDLING		0		0		0		N	
		4000254 GR-FIREARM REPLACEMENT		460		460		0		N	
Service Total:				460		460		0			

Condition	p
Problem/Notes	Rifle fires when closing bolt. Trigger adjusting stop screw has been removed from the housing. Trigger adjusting screws re-set. Bolt face pitted. Bore heat checked. Mfg. 1972 Offer spec. price on new rifle. Sendero only 25-06 available. Discount MSP 33%.
Repairman	Proof
Clean	Test
Target	Pattern
Gallery Tester	Date
Date	Date