

Serial Number: ML060434

Model ID: 700ML



RE00002059

Charge 2293001

1/10/2000

Will fire when the safety is pushed off

Upon receipt we could not duplicate
the reported concern, but did find the inside
of the trigger guard & bolt cover rusty.
Bolt & trigger guard were cleaned properly.

Repair at 50% of cost

1007
4015

[Signature]