

ALDER RUN SHOP
1402 GALLUP RD.
Franklin, VT 05457
802-285-6431
Customer # 82766

January 5, 2000

Remington Arms
Service Dept.
14 Hoefler Ave
Union, NY 13357

Dear Repair Service Rep:

The enclosed muzzleloader model 700 camo, S.S, with
S/N MLO60434 was brought back by our customer because
the gun will fire when the safety is pushed off, by itself.
There is an obvious trigger problem with this gun.

Please repair and return to our address above
as soon as possible. Any questions, please call 802-285-6431.
Thank you.

Cordially yours

Richard D. Brown

RE: Gun fires by itself
when safety is pushed off