

Dear Remington,

I was directed through correspondence from Customer Help correspondence attached, to ship this Model 700 to you. See the email enclosed.

The email asked me to provide basic information as follows:

Type Rifle: Model 700 Remington .270 caliber, black, synthetic stock, serial number E6746746.

Problem: When the Safety is in S and you place it to F (fire), it discharges. This rifle has done it twice while loaded and fired the shell (twice). When trying to duplicate the fault, sometimes it does, and sometimes it doesn't fire when taking the Safety from S to F. To repeat, it doesn't do it every time, but it does it. Obviously, we've stopped loading it and feel very unsafe to use it as is. Also, bullets jam when extracting the first shell on occasion. We need your help desperately.

Return Address: Jim Allen
22960 Palisades Drive
Lebanon, MO 65536

Phone after 5:00 p.m. Central Daylight Savings
Time is 417-532-5751. Work Phone is 573-596-0622. Email is
or

Jim Allen 11/23/04
Thanks, Jim Allen
Could not duplicate concern
Try assm. Rusty. Replace w/new
OPA at H/C to restore
confidence

NUMBER-
E6746746

Model: **700**



RE00088786

1007
4015