

Remington Arms Company, Inc.

870 Remington Dr. P.O. Box 700
Madison, NC 27025-0700

Parts/Repairs 800-243-9700
Fax 336-548-7801

www.remington.com info@remington.com

REPAIR DOCUMENT

REPAIR DOCUMENT

Repair Order Number RE00044289 Account # - R-	Description/Serial Number 56933 Model 721 Center Fire Caliber: 270	Date Received - 4/24/2002 Estimate Date - 4/4/2002 Current Date - 4/30/2002
Customer ALLISON AND CAREY GUN WORKS 17311 S E STARK PORTLAND, OR 97233 US Phone (H) (503)-256-5166 Phone (W)	Return To ALLISON AND CAREY GUN WORKS 17311 S E STARK PORTLAND, OR 97233 US Fax Email	

Problems			
Reported		Found	
M123	FORWARD TO PRODUCT SERVICE FOR INSPECTION	M178	TRIG ADJ SCREWS RESET, CANNOT R
M992	FIRE WHEN SAFETY WAS TAKEN OFF	M239	REPLACE TRIGGER ASSEMBLY

Technician's Comments	
ProblemNotes	Gun's MFG date was 4/71. Action and trigger assy. is very dirty. Quoted for replacing trigger assy. at the cost of the safety lever modification program. NOTE the rec. and stock need to be altered to accept the new style safety lever.

Parts and Labor			
Material #	Material Description	Quantity	Warranty (Y/N)
Part			
F26345	700 TRIG ASSB RH	1	Y
Part Total:		1	
Service			
4000104	ARMS SERV SHIPPING & HANDLING	0	Y
4000116	GR-LABOR	20	N
4000118	GR-CLEAN	1	Y
4000119	GR-TEST	1	Y
4000294	GR-CHECK TPA	1	Y
Service Total:		23	


10 LBS 1 OF 1

REMINGTON ARMS CO INC
800 243-9700
14 HOEFLER AVE
ILION NY 13357

SHIP

TO:

ALLISON AND CAREY GUN WORKS
17311 S E STARK
PORTLAND OR 97233




OR 972 9-04



UPS GROUND

TRACKING #: 1Z 114 813 03 1187 7146



BILLING: PREPAID

INV#: RE00044289

ASC 3.70 J69X/J64X 14.0 01/2002