

6.5#

4/97

could not duplicate concern.
Found trig. pin rusty & Trig.
sluggish. ~~Replace~~/REPAIR
AS needed & replace TPA
AT N/K * # 230145

Serial
Number:

ML068505

Model: 700ML



RE00088573

1007
4015

4/97