Date: 12/1/04
By: Bruce Travis Sn.

FIREARM INSPECTION WORKSHEET

BACKGROUND
Customer name: Clint Alsbury
R.E. Number: \$\forall 5\forall 5\forall 7
Reason for inspection: FSR
FIREARM
Manufacturer: Rem. Model: 700
Serial Number: ML 068505 Date of Manufacture: 4/97
Overall external condition: Cool
Barrel condition: 012AY
Receiver condition: 0 444
Stock condition: 012 44
Bolt/firing pin condition:
Trigger assembly condition:
Engagement:
Adjustments/alterations:
Other: TRIG. PIN RUSTY
Headspace:
Function evaluation:

Feeding:
Extraction/ejection:
Trigger pull: 6.5 th
Manual safety:
Test firing results (if applicable):
DISPOSITION
could not duplicate concern, Found Trig. PIN RUSTY
could not duplicate concern, Found Trig. PIN RUSTY Trig sluggish. Repair As needed a Replace TRA out N.
ADDITIONAL COMMENTS