

Repair Order Number



Repair Order Number RE00084679	Description/Serial Number S6479412	Repairman - Robert Frink Date Received - 9/10/2004
Account # - R-	Model 700 Center Fire Caliber: 223 LSS WITH THUMBHOLE STOCK	Estimate Date - Current Date - 9/20/2004
Customer AMERICAN SHOOTERS SUPPLY 1702 CENTRAL AVENUE ALBA Y, NY 12205 US	Return To AMERICAN SHOOTERS SUPPLY 1702 CENTRAL AVENUE ALBA Y, NY 12205 US	
Phone (H) (518)-862-9842 Phone (W)	Fax Email	

Reported		Problems		Found	
M123	FORWARD TO PRODUCT SERVICE FOR INSPECTION	M123	FORWARD TO PRODUCT SERVICE FOR		
M992	FIRES WHEN TAKEN OFF SAFE				

Material #		MaterialDesc	Quantity Needed	Quantity From Inv	Quantity From Kit	Warranty (Y/N)
Part						
F97490		700 SS TRIG ASSB RH	1	1	0	N
Part Total:			1	1	0	
Service						
4000104		ARMS SERV SHIPPING & HANDLING	0	0	0	N
4000119		GR-TEST	1	1	0	N
Service Total:			1	1	0	

ProblemNotes	Trigger adjusting screws altered beyond limits. (Trigger would not return to position). Replace trigger assembly at 1/2 MSP. Function test.				
Repairman	Proof	Clean	Test	Target	Pattern
Gallery Tester	Date	Date	Date	Date	Date