

7.5# 5/01



3/26/2005

SAFETY ISSUE

95315

Remington
Arm Service Div

Enclosed Remington 700 BDL 7-08 #E6733761
is returned for warranty repair. Customer states
gun will fire when bolt is closed. This does
not happen all the time. Customer says
this gun has been back for same reason before.
He is getting extremely uncomfortable with this
gun. Please exchange gun or trigger
assembly. Questions please call undersign.

Thanks
Mike

12 1250

E6733761

Model: 700



RE00095315

Exchange for new RMAC 27357

Charge 230145 FLS 4/5/05

*
* check over cust. rifle - replace
TPA & WIP

0907 • Phone: (706) 863-4868 • Fax: (706) 863-1558