

WILLIAM E. POULSON

268 Almon Court
Martinez, Georgia 30907
706-863-2596
Fax 706-869-0639
yardandgarden@bellsouth.net

April 3, 2004

Dear Remington repair,

This model 7 cal 708 Sn: 7648637, has developed a problem where the sear does not capture the hammer. Also when it does it will sometime fire when the safe is removed. Please repair and E mail or Fax me the cost with a repair number and I will mail a check immediately.

Sincerely,

Bill Poulson
Bill Poulson

*Set screws altered, Trig. is contaminated
w/ a sticky lubrication residue, replace
Trig. ASSM. checkover + repair @ 1/2 MSP
BWT*

Dom 4/15/1988

Serial
Number:

7648637

Model: 7



RE00079865