

Serial
Number:

E6733761

Model: 700



RE00061250

2/10/23

Rust found at trigger hole
& on trigger -

Small metal chip found inside the
housing

Rust at trigger could have seized trigger -

Replace trigger assembly at no charge -

Charge 230145