

To whom it may concern: on oct. 3 03
while hunting for sitka blacktail deer in
Podiak Alaska my Model 700 BDL
Remington 30 06 fired 3 times as
I was switching the safety switch
from "safe" position to the "fire" position.

To clarify: the rifle actually fired without
any fingers on triggers when the safety
fully landed in the fire position. This
bloodied my right thumb 2 times. no
one was hurt except my hand and
my nerve. please inform me of any
information you have regarding this
condition of this model of this rifle.

If repairs are possible please do them,
if replacement is appropriate please
do it.

(907) 262
3788

P.S. upon further
thought and additional
information I would
like this rifle replaced
as the same irregularity
happened again in front (witnessed) by my local
gunsmith.

sincerely
Brannon Ames
Soldotna, Alaska
99669

137 Cornsforth

sincerely Brannon Ames